

Exam conducted Nov. 7, 2012 to determine location and status of Irrigation use for CSRBA Claim 94-4059. IDWR Staff had previously seen Irrigation on the property but not determined the amount of irrigated area or location of the Irrigation Place of Use (POU).

DIVERSION AND DELIVERY SYSTEM: Two shallow irrigation wells are present & were constructed before IDWR Driller's Reports were required. One well is on each side of Old River Road near the buildings shown on the attached USGS map. An irrigation pipe hauling trailer was seen near the wells on the property but other Irrigation equipment had been removed for the season.

IRRIGATED POU: Claim 94-4059 is based on a Statutory Claim for 57 acres signed in 1980. Aerial Photos from 1993 to 2014 show a large excavated pond at the North East end of the claimed Irrigation POU. The pond is not shown on the 1985 topographic map of the area. Map notes show 1977 air photos were used to update the map. Irrigated acres 46.6.



Orange Windsock in POU N of Road 11.7.2012



View across Irrigation POU toward CDA River

SCANNED

APR 14 2015



94-4059 View across Irrigation POU



94-4059 View E to W Large Pond NE edge of Irrigation POU



94-4059 View across Irrigation POU

Shaun M. Maxey, Senior Water Resource Agent, IDWR, Northern Region