

Identify

Identify from:
Taxlots

Taxlots
FOSTER, JAMES T

Location:
2,294,615.310 1,826,900.64

Field	Value
ID	4187025
UPDATED	5/19/2014
PIN	005150010010
OWNER	FOSTER, JAMES T
ADDRESS1	PO BOX 911
ADDRESS2	
CITY	COEUR D ALENE
STATE	ID
ZIPCODE	83816
P_ADDRESS	7069 S KODIAK RD
P_ZIPCODE	
SUB_NAME	BEAR MEADOWS
LEGAL1	BEAR MEADOWS, LT 1 BLK 1
LEGAL2	537- IMP RES RURAL SUB
LEGAL3	
LEGAL4	
LEGAL5	
LEGAL6	<null>
ACRES	6
COUNTY	Kootenai
SOURCE	
YEAR_BUILT	2007

Identified 1 feature

Table Of Contents
Identify

SCANNED
MAY 11 2015

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

1. WELL TAG NO. D0054099

DRILLING PERMIT NO. 849326

Water Right or Injection Well No.

2. OWNER:

Name: Leon Mete

Address: 9323 North Government Way #235

City: Hayden State: ID Zip: 53535

3. LOCATION OF WELL by legal description:

Twp. 49N

Rge. 3W

Sec. 9

NE 1/4 SW 1/4

Gov't Lot County Kootenai

Address of well site: Hwy 97 - 16055 South

City: Coeur d'Alene

4. USE: Domestic

5. TYPE OF WORK: New Well

6. DRILL METHOD: Air Rotary

7. SEALING PROCEDURES:

Seal Material	From	To	Wt/Volume	Seal Placement Method
Bentonite	0	37	550	Pour

Was drive shoe used? yes Shoe Depth 37

Was drive shoe seal tested? yes How? air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing or Liner	Welded or Threaded
6"	+3	37	250	Steel	casing	welded
4"	-10	250	160	PVC	Liner	glued

Length of Headpipe Length of Tailpipe

Packer? No

9. PERFORATIONS/SCREENS PACKER TYPE:

Perforation Method Drill

Screen Type & Method of Installation

From	To	Slot Size	Number	Diam.	Material	Casing or Liner
230	210	1"	16	4"	PVC	Liner
190	170	1"	16	4"	PVC	Liner
150	130	1"	16	4"	PVC	Liner

10. FILTER PACK NONE

Filter Material	From	To	Wt./Volume	Placement Method
NONE				

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

40 ft. below ground Artesian pressure lb.

Depth flow encountered 205 ft.

Describe access port or control devices: cap

Office Use Only

Well ID No.

Inspected by

Twp. 1/4 Rge. 1/4 Sec. 1/4

Lat: Long:

12. WELL TESTS:

☐ Pump	☐ Bailer	☒ Air	☐ Flowing Artesian
Yield gal./min	Drawdown	Pumping Level	Time
100			2 hrs.

Water Temp: 50 deg. Bottom Hole Temp:

Water Quality test comments: good, clear, no odor

Depth first water encounter 140

13. LITHOLOGIC LOG:(Describe repairs or abandonment)

Bore Dia.	From	To	Remarks:(Lithology) (water quality, temp)	Water
8"	0 ft	2 ft	Topsoil	Y N
8"	2 ft	10 ft	Redish Brown clay	
8"	10 ft	14 ft	Basalt Boulders	
8"	14 ft	20 ft	Broken Basalt & brn. Clay	
8"	20 ft	25 ft	Basalt Boulders	
8"	25 ft	83 ft	hard black basalt	
6"	83 ft	92 ft	broken basalt	
6"	92 ft	135 ft	hard basalt	
6"	135 ft	140 ft	med. Hard basalt	X
6"	140 ft	155 ft	brown clay & basalt	
6"	155 ft	185 ft	brown clay	
6"	185 ft	205 ft	brown clay and basalt	
6"	205 ft	250 ft	basalt, gray sand, & gravel	

RECEIVED

OCT 10 2007

IDWR/North

Completed Depth 250 (Measurable) 250

Date: Started 9/20/07 Completed 9/21/07

14: DRILLER'S CERTIFICATION

Company Name: ALL-WAYS DRILLING, INC.

FIRM #: 510

Principal Driller Stanley K. Wolf Date 10/7/07

Driller or Operator 2 Date

Operator 1 Stanley K. Wolf Date 10/7/07

49N 3W 9

SCANNED

MAY 11 2015