

FIELD EXAMINATION OF CSRBA WATER RIGHT CLAIM

Claim Identification Number: 95-4617

Date of Examination: July 29, 2015

Approximate Time of Examination: 11:15 am

IDWR Field Staff: Evan Roda, Linda Werner

Examination Location: T47N R04W S04 Lot 4 SWNE

Purpose of Visit: Locate and document spring POD location

Field Examination Results: Met with claimant's neighbor and long time resident of the area, Jack Hansen, who was able to take us to the spring location and diversion works. GPS waypoint and photos taken at spring location / cistern. Horizontal GPS accuracy was within 18.5 feet. Spring located at N 47° 26.830', W 116° 50.311'



1) Spring location / cistern

SCANNED
JUL 30 2015



2) Water access hose at roadway approximately 15 feet below cistern



3) Jack Hansen showing water access hose



4) Overflow below cistern