

FIELD EXAMINATION OF CSRBA WATER RIGHT CLAIM

Claim Identification Number: 95-13481

Date of Examination: July 29, 2015

Approximate Time of Examination: 12:15 pm

IDWR Field Staff: Evan Roda, Linda Werner

Examination Location: T47N R04W S03 Lot 5 NWSW

Purpose of Visit: Locate and document spring POD location

Field Examination Results: Met with claimant's neighbor and long time resident of the area, Robert Palm, who was able to take us to the spring location and diversion works. GPS waypoint and photos taken at spring location / cistern. Horizontal GPS accuracy was within 19.5 feet. Spring located at N 47° 26.639', W 116° 49.926'



1) Spring location / 13,000 gal. cistern



2) Undeveloped spring approximately 60'+/-
NE of developed spring

SCANNED
JUL 31 2015