RECEIVED

AUG 0 3 2000

IDWR/North

8/18/00 D

Form 238-11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 00 13790
DRILLING PERMIT NO. _____
Other IDWR No. 765474

POSTED

2. OWNER:
Name Fred Mohs
Address 26153 S. Hwy 97
City Harrison St Maries State ID Zip 83861

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 47N North ☑ or South ☐
Rge. 3 East ☐ or West ☑
Sec. 8, ____ 1/4 SW 1/4 NE 1/4
Gov't Lot ____ County Kootenai
Lat: : : Long: : :

Address of Well Site _____
Mile Post 65½ on Hwy 97 City St Maries
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	61	8	Pour

Was drive shoe used? ☑ Y ☐ N Shoe Depth(s) 61 Feet
Was drive shoe seal tested? ☐ Y ☑ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	-61	.250	Steel	☑	☐	☑	☐
4	-10	-130	160	PVC	☐	☑	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
Perforations Method Drill
Screens Screen Type _____

From	To	~~Slot Size~~	Number	Diameter	Material	Casing	Liner
-90	-130	½	48		PVC	☐	☑
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
20 ft. below ground Artesian pressure ____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: Well Cap

11. WELL TESTS:
☐ Pump ☐ Bailer ~~☐ Air~~ ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
30+	Airlift from	130 ft	

Water Temp. 52° Bottom hole temp. ____
Water Quality test or comments: Clear tasteless or odorless
Depth first Water Encounter 61'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	5	Top Soil		✓
8	5	48	Clay - Brown		✓
8"	48	61	Basalt Broken	✓	
6"	61	75	Basalt Broken		✓
6"	75	130	Basalt Broken Brown	✓	

RECEIVED
OCT 20 2000
Department of Water Resources

Completed Depth 130' (Measurable)
Date: Started July 12 Completed July 13th

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Allwest Drilling Firm No. 370
Firm Official Stanley Kidd Date 7/29/00
and
Driller or Operator Chris Kerns Date 7/29/00
(Sign once if Firm Official & Operator)

47N 3W 8

FORWARD WHITE COPY TO WATER RESOURCES