RECEIVED
JUL 18 2002
IDWR/North

RECEIVED
OCT 01 2015
IDWR/NORTH

Form 238-7 11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 0022347
DRILLING PERMIT NO. 780232
Other IDWR No.

POSTED

2. OWNER:
Name John Uriguen
Address 2009 N. 12th
City Coeur d'Alene State ID Zip 83814

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp 48 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 5 NW 1/4 (10 acres) SW 1/4 (40 acres) NW 1/4 (160 acres)
Gov't Lot ____ County Kootenai
Lat: : : Long: : :
Address of Well Site 7711 W. Silo Ridge Road
(Give street name of road + Distance to road or Landmark)
City Coeur d'Alene
Lt. ____ Blk. ____ Sub. Name ____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	39	350#	dry granular

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 39'
Was drive shoe seal tested? ☐ Y ☐ N How? ____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	39	250	Steel	☒	☐	☐	☐
4"	5	325	160	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
☒ Perforations Method saw cut 1/8"x 6"
Screens Screen Type ____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
305	325		60			☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
63 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: ____

11. WELL TESTS:
Drilled ☐ Pumped ☐ Bailed ☐ Air ☐ Flowing Artesian

Yield gal./min	Drawdown	Pumping Level	Time
24 - 25			4 hrs.

Water Temp. ____ Bottom hole temp. ____
Water Quality test or comments: ____
Depth first Water Encounter 64'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	8	Fill dirt		
	8	15	Shale, decomposed, tan		
	15	24	Shale, hard & soft, tan & gray		
	24	29	Shale, green, soft		
	29	34	Shale, brown, decomposed		
	34	39	Shale, grey, green		
6	39	46	Shale, green		
	46	58	Shale, tan		
	58	74	Shale, grey, blk & wht 1/2 gpm	x	
	74	90	Shale, grey, dark		
	90	131	Shale, black & white		
	131	139	Shale, green		
	139	146	Shale, grey		
	146	168	Shale, grey, green		
	168	196	Shale, dark grey		
	196	216	Shale, black & white		
	216	248	Shale, green		
	248	266	Shale, green grey		
	266	276	Shale, black 20 gpm	x	
	276	291	Shale, green 3 gpm	x	
	291	325	Shale, black 2 gpm	x	

Completed Depth 325' (Measurable)
Date: Started 7-10-02 Completed 7-12-02

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name McCarty Drilling & Pump Inc. Firm No. 586
Firm Official [signature] Date 7-15-02
and
Driller or Operator ____ Date ____
(Sign once if Firm Official & Operator)

48N 4W 5

FORWARD WHITE COPY TO WATER RESOURCES