

RECEIVED

Form JUN 16 1999
11/97

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

IDWR/North

D 0010087

076658

1. WELL TAG NO. D
DRILLING PERMIT NO. 95-PP-N-58
Other IDWR No.

2. OWNER:
Name Estate of John L. Toedter - Robert Toedter PR.
Address 727 Starlight Dr.
City Billings State MT Zip 59101

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

POSTED

N
W
E
S

		X	

Twp. 49 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. B 1/4 SW 1/4 SE 1/4
Gov't Lot County Kootenai
Lat. Long.
Address of Well Site 7461 Hwy 95 E.
1/4 mile on Patnam rd. City Coeur d'Alene
(Give at least name of road + Distance to Road or Landmark)

Lt. Blk. Sub. Name

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
CASING SEAL	1	34	8 sacks	POURED

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 34'

Was drive shoe seal tested? ☐ Y ☒ N How? Air Pressure

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	1	34	250	STEEL	☒	☐	☒	☐
4"	7	427	100	PVC	☐	☒	☐	☐

Length of Headpipe Length of Tailpipe

9. PERFORATIONS/SCREENS

Perforations Method Saw cut

Screens Screen Type

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
87'	107'	3/4"	36	4"	PVC	☐	☒
387'	427'	"	72	4"	PVC	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

15' ft. below ground Artesian pressure lb.

Depth flow encountered ft. Describe access port or

control devices: Bolted Well Cap

11. WELL TESTS:

☐ Pump ☐ Bailor

Office Use Only
Inspected by
Twp Rge Sec
1/4 1/4 1/4
Lat. : : Long. : :
☒ Air ☐ Flowing Artesian

Yield gal/min	Drawdown	Pumping Level	Time
Approx - 2% - 3			

Water Temp. Cool Bottom hole temp. Cool

Water Quality test or comments: Good

Depth first Water Encounter 77'

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Water

Bore Dia	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8"	0	34'			
6"	34	427'			
	0	5	top soil & Clay		X
	5	13	Decomposed Granite		X
	13	28	Decomposed Granite w/ hard streaks		X
	28	427'	(Hard) Granite	X	

Completed Depth 427' (Measurable)

Date: Started 5-24-99 Completed 5-26-99

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

AQUA DRILLING & EXPLORATION INC. Firm No. 163

Firm Official Scott M. Baur Date

and Driller or Operator Wayne Miller Date 5-28-99

(Sign once if Firm Official & Operator)

49N 4W 8

FORWARD WHITE COPY TO WATER RESOURCES

SCANNED

OCT 22 2015