

Identify

Identify from:
Taxlots

Taxlots

Location:
2,282,669.163 1,820,133.248 Meters

Field	Value
ID	5246320
UPDATED	9/28/2015
PIN	49N04W324800
OWNER	
ADDRESS1	13649 S BELLGROVE RD
ADDRESS2	
CITY	COEUR D ALENE
STATE	ID
ZIPCODE	83814
P_ADDRESS	13649 S BELLGROVE RD
P_ZIPCODE	
SUB_NAME	
LEGAL1	TAX #18738 [IN NE-SW]
LEGAL2	
LEGAL3	
LEGAL4	
LEGAL5	
LEGAL6	<null>
ACRES	0
COUNTY	Kootenai
SOURCE	
YEAR_BUILT	2001

Identified 1 feature

Table Of Contents
Identify

SCANNED
DEC 18 2015

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Office Use Only		
Inspected by		
Twp	Rge	Sec
1/4	1/4	1/4
Lat	:	Long
:	:	:

1. WELL TAG NO. D0013471 JUL 26 2000

Drilling Permit No:

Other IDWR No.

7125576 IDWB/North

2. OWNER

Well Number:


Name Gail & Michael Gneckow

65

Address 758 Meadowood DriveCity SandpointState WA Zip 83864

3. LOCATION OF WELL by legal description

sketch map location must agree with written location

Twp. 49 ☒ North or ☐ SouthRge. 04 ☐ East or ☒ WestSec. 32 1/4 NE 1/4 SW 1/4Gov't Lot _____ County KOOTENAI

Lat: _____ Long: _____

Address of Well Site Hamacker RoadCity Coeur d'Alene

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
BENTONITE	0	18	8 sacks	overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 18Was drive shoe seal tested? ☒ Y ☐ N How? air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
4	5	620	160	pvc	☐	☒	☐	☐
6	2	58	.250	steel	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☒ Perforations Method skill saw☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
580	620	6	115	4	pvc	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

160 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
3			

Water Temp. _____ Bottom Hole Temp _____

Water Quality test or comments: _____

Depth first Water encountered 140

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Depth	From	To	Remarks: Lithology, Water Quality, Temperature	Water	
				Y	N
8	0	15	Topsoil, sand	☐	☒
8	15	58	Decomposed granite brown & white	☐	☒
8	58	140	Decomposed granite black & white	☐	☒
8	140	160	Granite firm black & white w/green w/	☒	☐
8	160	180	Granite firm black & white w/green w/	☒	☐
8	180	350	Granite firm black & white w/green	☐	☒
8	350	360	Granite firm black & white w/green w/	☒	☐
8	360	420	Granite firm black & white w/green	☐	☒
8	420	620	Granite firm black & white	☐	☒

RECEIVED

OCT 20 2000

Department of Water Resources

Completed Depth 620 (Measurable)
Date: Started 7/17/00 Completed 7/19/00

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name 4120 WellService, Inc. Firm No. 448Firm Official Mark R. Rupp Date 7-24-00and Supervisor or Operator Michael Haltermann Date 7-24-00(Sign Once if Firm Official and Operator)
Michael Haltermann

49 N 4 W 32

SCANNED

DEC 18 2015