

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
	1/4	1/4	1/4
Lat:	:	Long:	:

1. WELL TAG NO. D. 0033954
DRILLING PERMIT NO. 826196
Water Right or Injection Well No. _____

2. OWNER:
Name Duddleston, James & Karen Larson
Address 1912 Glenview Dr.
City Las Vegas State NV Zip 89134

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 49 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 1 1/4 SW 1/4 SW 1/4
Gov't Lot _____ County Kootenai

Lat: _____ Long: _____
Address of Well Site SWIDE Bay Rd.
off of Vallhalla Rd City CDA.
(Give at least name of road + Distance to Road or Landmark)
Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply

(Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite	0	22	8 SACS	Poured

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 22
Was drive shoe seal tested? ☒ Y ☐ N How? AIR PRESSURE

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6" +1	-22	250		STEEL	☒	☐	☒	☐
4" -9	-802	160		PVC	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____
Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method SAWCUT

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
842	662	1/2 x 5	40	4"	PVC	☐	☒
682	702	"	"	"	"	☐	☒
722	742	"	"	"	"	☐	☒
762	802	"	"	"	"	☐	☒

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

40 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: Bolted well cap

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
2			

Water Temp. Cool Bottom hole temp. Cool

Water Quality test or comments: Good

Depth first Water Encounter 300'

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	22			
6	22	802			
	0	8	Broken Basalt & Clay		X
	8	19	Decomposed Granite		X
	19	245	Granite		X
	245	302	Granite w/soft spots	X	
	302	802	Granite	X	

RECEIVED
OCT 05 2004
IDWR/North

SCANNED
FEB 03 2016

Completed Depth 802' (Measurable)

Date: Started 8-18-04 Completed 8-24-04

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name AQUA DRILLING & EXPLORATION INC. Firm No. 163

Principal Driller Scott H. Saunders Date _____

and Driller or Operator II Wayne Miller Date 8-26-04

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.