Form 238-7
3/95-C96

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 82-6-027-____
Other IDWR No. D0035507

2. OWNER:
Name Duane Anderson
Address 3807 Belmont Road
City Coeur d'Alene State ID Zip 83858

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location

N

W ☐ E

S

Twp. 52 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 33 1/4 (10 acres) NE 1/4 (40 acres) SW 1/4 (160 acres)

Gov't lot _____ County Kootenai
Lat: : : Long: : :
Address of Well Site E.end of Forestdale Drive, rt at culdesac City Rathdrum
(Give at least name of road + Distance to Road or Landmark)
Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	18	450#	dry granular

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	291	250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☐ Perforations Method _____
☒ Screens Screen Type johnson ss telescoping

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
291	296	25		6"	SS	☒	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
248 ft. below ground Artesian Pressure ____ lb
Depth flow encountered ____ ft. Describe access port or control devices: _____

5 2N 4W 33

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal/min.	Drawdown	Pumping Level	Time
50+			4 hrs

Water Temp. _____ Bottom hole temp. _____
Water Quality test or comments: Cold & clear, no sand
Depth first Water Encountered 265'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia	From	To	Remarks: Lithology, Water Quality & Temp.	Water Y	Water N
10"	0	2	Topsoil	☐	☒
	2	4	Topsoil, gravel	☐	☒
	4	18	Gravel, sand	☐	☒
8"	18	33	Gravel, sand	☐	☒
	33	46	Gravel, coarse	☐	☒
	46	63	Cobbles, gravel, coarse	☐	☒
	63	81	Gravel, medium	☐	☒
	81	112	Gravel, sand	☐	☒
	112	116	Sand	☐	☒
	116	134	Gravel, sand	☐	☒
	134	168	Gravel, coarse	☐	☒
	168	171	Boulder	☐	☒
	171	189	Gravel, sand	☐	☒
	189	215	Gravel, cobbles	☐	☒
	215	265	Gravel, cobbles, sand	☐	☒
	265	285	Gravel, sand, silt, brown	☒	☐
	285	290	Gravel, sand, coarse	☒	☐
	290	300	Gravel, coarse with sand	☒	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐
				☐	☐

Completed Depth: 296 (Measurable)
Date: Started 11/08/04 Completed 11/11/04

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name McCarty Drilling & Pump Inc Firm No. 586
Firm Official Scott McCarty Date 11-12-04
Supervisor or Operator _____ Date _____
(Sign once if Firm Official & Operator)

Date: 11/12/2004 Time:2:20 PM