




WELL DRILLER'S REPORT

RECEIVED

77146

1. WELL TAG NO. D 10876
 DRILLING PERMIT NO. 96-99-N-271 NOV 19 1999
 Other IDWR No. 96-99-N-271

11. WELL TESTS:

☐ Pump ☐ Bailer

2. OWNER: AI and Daryl Kyle IDWR/North
Name
Address E. 9105 Bunco Rd.
City Arbol State Id Zip 83801

Yield gal./min.	Drawdown	Pumping Level	Time
60			4 Hours

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

Depth first Water Encounter 70

12. LITHOLOGIC LOG: (Describe repairs or abandonment) water

[illegible]

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Hester Well Drilling Farm No. 528

Firm Official [Signature] Date 11-16-95

and
Driller or Operator Mark Hersley Date 11-2-99

(Sign once if Firm Official & Operator)

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

70 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or
control devices:

53N 3W 35 FORWARD WHITE COPY TO WATER RESOURCES