

Identify

Identify from:

Taxlots

☒ Taxlots

HANCOCK, RONALD W

Location:

2,304,314.608 1,832,788.257 Meter

Field	Value
ID	7545850
UPDATED	10/12/2016
PIN	50N02W215450
OWNER	HANCOCK, RONALD W
ADDRESS1	2216 S WOLF LODGE CREEK RD
ADDRESS2	<null>
CITY	COEUR D ALENE
STATE	ID
ZIPCODE	83814
P_ADDRESS	2216 S WOLF LODGE CREEK RD
P_ZIPCODE	<null>
SUB_NAME	
LEGAL1	PTN TAX #12581 LYING E OF CO RD EX
LEGAL2	<null>
LEGAL3	<null>
LEGAL4	<null>
LEGAL5	<null>
LEGAL6	<null>
ACRES	1.1
COUNTY	Kootenai
SOURCE	<null>
YEAR_BUILT	1996

Identified 1 feature

Table Of Contents

Identify


Other IDWR No. _____

Use Typewriter or Ballpoint Pen

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
_____ 1/4 _____ 1/4 _____ 1/4
Lat: : : Long: : :

Address **P.O. BOX 1581**
City **HAYDEN** State **MD** Zip **83835**

Sketch map location must agree with written location.



Twp. 50N North ☒ or South ☐
 Rge. 2W East ☐ or West ☒
 Sec. 21 1/4 1/4 1/4 1/4
 Gov't Lot _____ County Kootenai
 Lat. : : Long. : :
 Address of Well Site BACKSIDE OF HAYDEN LAKE
 City _____

Lt. _____ Blk. _____ Sub. Name _____

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	+20	7 bags	pour in

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 51 feet

Was drive shoe seal tested? ☐ Y ☒ N How?

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8"	+2	55	.025	steel	☒	☐	☒	☐
4"	20	200	1	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

Perforations	Method <u>Drill</u>
Screens	Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Line
140'	200'		200	3/8"	PVC	☐	☒
						☐	☐
						☐	☐

15	ft. below ground	Artesian pressure	lb.
----	------------------	-------------------	-----

Depth flow encountered _____ ft. Describe access port or _____

control devices: _____

☐ Pump ☐ Bailer

Yield gal./min.	Drawdown	Pumping Level	Time
9.5 GPM			2 hrs.

Water Temp. **cold** Bottom hole **cold** **cold**

Water Quality test or comments: clear, cold, no smell

Depth first Water Encountered

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

[illegible]

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name **United Drilling Inc.** Firm No. **414**

Firm Official Li R. V. S. Date 5/03/98

and

Supervisor or Operator Jason C. Beckham Date 5-3-96

(Sign once if Firm Official & Operator)

Control devices: NW3W 21 50N 2W

FORWARD WHITE COPY TO WATER RESOURCES