

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

1. WELL TAG NO. D D 0040298
DRILLING PERMIT NO. 834485
Water Right or Injection Well No. _____

2. OWNER:
Name Kenneth Addington
Address P.O. Box 340
City Harrison State ID Zip 83833

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 47 North ☒ or South ☐
Rge. 3 East ☐ or West ☒
Sec. 7 1/4 NW 1/4 SE 1/4
Gov't Lot _____ County Kootenai

Lat: _____ Long: _____
Address of Well Site 1905 E Crows Nest Rd.
City Harrison

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply

(Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite	0	70	23 sk	Pour Around Pipe

Was drive shoe used? ☒ ☐ N Shoe Depth(s) 178
Was drive shoe seal tested? ☒ ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	-178	250	Steel	☒	☐	☒	☐
4"	-12	-562	160	PVC	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____
Packer ☒ Y ☒ N Type Formation Packer @ 390

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method Drill
Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
-402	-442	3/4	40	4"	PVC	☐	☒
-502	-542	3/4	40	4"	PVC	☐	☒

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method
none				

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

393 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 395 ft. Describe access port or control devices:
Well Cap

17 N 3 W 7

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
5 gpm	Airlift	from	560'

Water Temp. 48° Bottom hole temp. _____

Water Quality test or comments: Clear no odor

Depth first Water Encounter 395

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8"	0	20	Basalt - Broken w/clay		
	20	23	Void		
	23	63	Basalt Broken w/clay		
	63	95	Basalt Broken		
	95	131	Clay - Brown		
	131	150	clay - tan		
	150	178	Basalt - Gray		
6"	178	320	Basalt - Gray		
	320	345	Clay - Brown		
	345	375	Clay - Tan		
	375	382	Clay - Brown		
	382	395	Basalt - Gray		
	395	400	Basalt - Gray w/water		
			5 gpm.		
	400	560	Basalt - Gray		
	560	562	Clay - Brown		

RECEIVED
AUG 25 2005
IDWR/FNorth

Completed Depth 562 (Measurable)

Date: Started 7-6-05 Completed 7-10-05

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Action Drilling INC. Firm No. 618

Principal Driller Alvin Carris Date 8-8-05

Driller or Operator II _____ Date _____

Operator I Alvin Carris Date 8-8-05

Principal Driller and Rig Operator Required.

Operator I must have signature of Driller/Operator II.