

Other IDWR No. _____

097056

☐ *Air ☐ Flowing Artesian

City **PUYALLUP** State **WA** Zip **98373**

Sketch map location must agree with written location.

Lt. _____ Blk. _____ Sub. Name _____

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

* ☐ New Well ☐ Modify ☐ Abandonment ☐ Other _____

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☒ N How? _____

Length of Headpipe _____ Length of Tailpipe _____

☐ Perforations Method air perforator

☐ Screens Screen Type _____

250 ft. below ground Artesian pressure _____ lb.
Depth flow encountered 250 ft. Describe access port or
control devices: **Steel cap welded**

FORWARD WHITE COPY TO WATER RESOURCES

☐ Pump ☐ Bailer

Water Temp. cold Bottom hole temp. cold
Water Quality test or comments: clear, cold, no smell

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name **United Drilling Inc.** Firm No. **414**

Firm Official Jason C. Beckham Date 8/06/96
and
Supervisor or Operator Jason C. Beckham Date 8/06/96

(Sign once if Firm Official & Operator)