RECEIVED
Form 238-7
3/95
AUG 0 7 1995
NORTHERN REGION
IDWR

COPY

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

POSTED

Office Use Only
Inspected by TDK
Twp 54N Rge 3W Sec 33
1/4 NE 1/4 NW 1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 96 - 95 - N - 175 -
Other IDWR No.

2. OWNER:
Name BILL ROSS
Address 1208 MONTANA AVE
City COEUR D'ALENE State ID Zip 83814

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S — X

Twp. 54 North ☒ or South ☐
Rge. 03 East ☐ or West ☒
Sec. 33, 1/4 NE (10 acres) 1/4 NE (160 acres) 1/4
Gov't Lot ____ County KOOTENAI
Lat: : : Long: : :
Address of Well Site HOMESTEAD RD
City
(Give at least name of road + Distance to Road or Landmark)
Lt. ____ Blk. ____ Sub. Name ____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	30	9 BAGS	OVERBORE

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s)
Was drive shoe seal tested? ☒ Y ☐ N How? DROVE INTO ROCK

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+3	150	.250	STEEL	☒	☐	☒	☐
4	-144	464	.160	PSI PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
☒ Perforations Method SKILL SAW
☐ Screens Screen Type

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
404	424	1/8x4	70	4"	PVC	☐	☒
444	464	1/8x4	70	4"	PVC	☐	☒
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
115 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices:
NE NE 33 54N 3W

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
50+			

Water Temp. ____ Bottom hole temp. ____
Water Quality test or comments: ____
Depth first Water Encountered ____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	4	TOP SOIL W/GRAVEL		X
8	4	48	SAND & GRAVEL W/CLAY		X
8	48	51	BOULDER		X
8	51	63	SAND & GRAVEL COARSE		X
8	63	95	SAND FINE		X
8	95	150	SAND & GRAVEL W/GRAY CLAY		X
6	150	176	GRANITE GREEN & WHITE W/ ROSE SOFT		X
6	176	195	GRANITE WHITE & GREEN W/ROSE MED SOFT		X
6	195	240	GRANITE WHITE & BLACK & ROSE MED		X
6	240	249	GRANITE WHITE & GREEN W/WATER APPROX 3 GPM	X	
6	249	314	GRANITE WHITE & BLACK & ROSE MED		X
6	314	350	GRANITE WHITE & GREEN & ROSE MED		X
6	350	451	GRANITE WHITE & BLACK & ROSE		X
6	450	455	GRANITE WHITE & GREEN W/WATER APPROX 50+ GPM	X	
6	455	464	GRANITE WHITE & BLACK ROSE		X

MICROFILMED
MAR 0 9 1999

Completed Depth 464' (Measurable)
Date: Started 07/21/95 Completed 07/24/95

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O WELL SERVICE INC Firm No. 448
Firm Official [signature] Date 8-4-95
and
Supervisor or Operator [signature] Date 8-3-95
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES

SCANNED
APR 0 6 2017

SCANNED
NOV - 4 2011

COPY