

State law requires that this report be filed with the Director, Department of Water Resources within 30 days after the completion or abandonment of the well.


1. WELL OWNER
Name Michael D. Brown
E. 2665 Seltice
Address Post Falls, ID 83854
Owner's Permit No. 95-86-N-36

2. NATURE OF WORK
☒ New well ☐ Deepened ☐ Replacement
☐ Abandoned (describe abandonment procedures such as materials, plug depths, etc. in lithologic log)

3. PROPOSED USE
☒ Domestic ☐ Irrigation ☐ Test ☐ Municipal
☐ Industrial ☐ Stock ☐ Waste Disposal or Injection
☐ Other _____ (specify type)

4. METHOD DRILLED
☒ Rotary ☒ Air ☐ Hydraulic ☐ Reverse rotary
☐ Cable ☐ Dug ☐ Other _____

5. WELL CONSTRUCTION
Casing schedule: ☒ Steel ☐ Concrete ☐ Other _____
Thickness _____ inches Diameter _____ inches From _____ feet To _____ feet
_____ inches _____ inches _____ feet _____ feet
_____ inches _____ inches _____ feet _____ feet
_____ inches _____ inches _____ feet _____ feet
Was casing drive shoe used? ☒ Yes ☐ No
Was a packer or seal used? ☐ Yes ☒ No
Perforated? ☐ Yes ☒ No
How perforated? ☐ Factory ☐ Knife ☐ Torch
Size of perforation _____ inches by _____ inches
Number _____ From _____ To _____
_____ perforations _____ feet _____ feet
_____ perforations _____ feet _____ feet
_____ perforations _____ feet _____ feet
Well screen installed? ☐ Yes ☒ No
Manufacturer's name _____
Type _____ Model No. _____
Diameter _____ Slot size _____ Set from _____ feet to _____ feet
Diameter _____ Slot size _____ Set from _____ feet to _____ feet
Gravel packed? ☐ Yes ☒ No ☐ Size of gravel _____
Placed from _____ feet to _____ feet
Surface seal depth 39 Material used in seal: ☐ Cement grout
☒ Bentonite ☐ Puddling clay ☐ _____
Sealing procedure used: ☐ Slurry pit ☐ Temp. surface casing
☒ Overbore to seal depth
Method of joining casing: ☐ Threaded ☒ Welded ☐ Solvent Weld
☐ Cemented between strata
Describe access port _____

6. LOCATION OF WELL
Sketch map location must agree with written location.

Subdivision Name _____
Lot No. _____ Block No. _____
County Kootenai
SW 1/4 SW 1/4 Sec. 9, T. 50N N/S, R. 5W E/W.

7. WATER LEVEL
Static water level 55 feet below land surface.
Flowing? ☐ Yes ☒ No G.P.M. flow _____
Artesian closed-in pressure _____ p.s.i.
Controlled by: ☐ Valve ☐ Cap ☐ Plug
Temperature _____ °F. Quality _____
Describe artesian or temperature zones below.

8. WELL TEST DATA
☐ Pump ☐ Bailor ☒ Air ☐ Other _____
Discharge G.P.M. Pumping Level Hours Pumped
4 GPM - ESTIMATED AIRLIFT

9. LITHOLOGIC LOG

Bore Diam.	Depth		Material	Water	
	From	To		Yes	No
10"	0	10	Dirt		X
10"	10	39	Granite, decomposed		X
6"	39	45	Granite, soft		
6"	45	75	Granite, medium		X
6"	75	90	Granite, fractured		
NO PVC Liner Installed					
6" Drive shoe installed					

10. Work started 4/21/86 finished 4/21/86

11. DRILLERS CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.
Firm Name RONDEROSA DRILLING Firm No. 228
E. 6010 Broadway
Address Spokane, WA 99212 Date 4/21/86
Signed by (Firm Official) W. Scott Barratt
and James M. Doyle
(Operator) James M. Doyle

SCANNED
MAY - 5 2009

