

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
	1/4	1/4	1/4
Lat:	:	:	Long: : :

1. WELL TAG NO. D 0041191
DRILLING PERMIT NO. 839157
Water Right or Injection Well No. _____

2. OWNER:

Name Alan Job
Address P.O. Box 724
City Spirit Lake State ID Zip 83869

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 54 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 24 1/4 SW 1/4 SW 1/4
Gov't Lot _____ County Bonner 10 acres 40 acres 160 acres

Lat: : : Long: : :
Address of Well Site Ellies Lane
City Spirit Lake

(Give at least name of road + Distance to Road or Landmark)
Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
bentonite	0	18	300lbs	overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 177ft
Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1 1/2	177	250	steel	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____
Packer ☒ Y ☐ N Type k-packer

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method _____
Screen Type & Method of Installation telescoping/stainless

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
177	182	20		5	steel	☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

137 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: cap

54 N SW 24

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
20		170-180	1 1/2 hr

Water Temp. cold Bottom hole temp. _____

Water Quality test or comments: clear

Depth first Water Encounter 137

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	18	sand&gravel		
6	18	80	sand&gravel		
	80	120	sand&pea gravel		
	120	130	brown clay&sand		
	130	183	sand some gravel	x	

RECEIVED
MAY 23 2006
IDWR/North

Completed Depth 183ft (Measurable)
Date: Started 4-12-06 Completed 4-14-06

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Bronson Water Wells Firm No. 360

Principal Driller Clint Bronson Date 4/17/06

and Driller or Operator II _____ Date _____

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.