

Form 238-7
11/98

AUG 10 1998

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ Long: _____

NORTHERN REGION

77794

1. WELL TAG NO. D5158

DRILLING PERMIT N

95-98-N-131

Other IDWR No

2. OWNER:

Name Greg Nearpass

Address 3507 Bucksin RD

City Coeur d'Alene

State ID

Zip 83815

3. LOCATION OF WELL by legal description:

N Twp 49N North ☒ or South ☐
Rge 04W East ☐ or West ☒
Sec 33 1/4 SW 1/4 SE 1/4
Gov't Lot 10 Ac 40 Ac 160 Ac
Lat _____ Long _____

Address of Well Site: (see next line)

95 to Rockford Bay Rd to Loffs Bay Rd Lot #3 City

Lot _____ Blk _____ Sub. Name (see next line)

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

SEAL/FILTER PACK			Amount	Method
Material	From	To	Sacks/Lbs	
Bentonite	0	18	8 Sacks	pour in

Drive Shoe Used? ☒ Y ☐ N Shoe Depth(s) 175

Drive Shoe Seal Tested? ☐ Y ☒ N How?

8. CASING/LINER

Diam	From	To	Gauge	Material	Casing	Liner	Weld	Thrded
6"	2	175	0.025	Steel	☒	☐	☒	☐
4"	140	360		PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length Headpipe _____ Length Tailpipe _____

9. PERFORATIONS/SCREENS

- ☒ Perforations? Method Drill
☐ Screens? Screen Type

From	To	Slot	Nmbr	Diam	Material	Casing	Liner
160	180		100	3/8"	PVC	☐	☒
200	220		100	3/8"	PVC	☐	☒
240	280		100	3/8"	PVC	☐	☒

10. STATIC WATER LEVEL or ARTESIAN PRESSURE

80 ft. below ground. Artesian pressure lb.
Depth flow encountered 180 ft. Describe access port or
control devices: Steel cap welded

11. WELL TESTS:

- ☐ Pump ☐ Baller ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pump Level	Time
3.5	100%	359	1 hr.

Water Temp. cold Bottom hole temp. cold

Water Quality test or comments: (below) Depth first Water Encountered 110

turbid, no smell

12. LITHOLOGIC LOG (Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality and Temperature	Water	
				Y	N
8	0	1	Topsoil	☐	☒
8	1	50	Clay - brown - medium	☐	☒
8	50	110	Clay - orange - soft	☐	☒
8	110	170	Clay & decomposed granite	☒	☐
			silt & water @ 112'	☐	☐
8	170	175	Granite - brown/white/black	☐	☒
			with mica & quartz - medium	☐	☒
6	175	215	Granite - brown/white/black	☐	☒
			with mica & quartz - medium	☐	☒
			3.5 gpm @ 180'	☐	☐
6	215	260	Granite - black & white - hard	☐	☒
6	260	281	Granite - white & green with quartz-soft	☐	☒
6	281	342	Granite - black & white - hard	☐	☒
6	342	360	Granite - black/white/green - hard	☐	☒

Completed Depth 360 (Measurable)

Date: Started 8/5/98 Completed 8/7/98

13. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name United Drilling Inc. Firm No 414
Firm Official _____ Date 8/7/98
Supervisor or Operator Jason C. Beckham Date 8/7/98

FORWARD WHITE COPY TO WATER RESOURCES

49 N 4W 33

CITY NO.	SUBD. NO.	BLOCK NO.	LOT & SPLIT NO.	GRANTOR	GRANTEE	REMARKS	DEED TYPE	DATE	BOOK & PAGE	SURVEY REF. NO.
0	5205 001	004-0		NENE PASS, MAEIAUA		PLATTED 41100410-33-8400 LOTS AFRU OF McREARD MEADOWS FOR 98	Part	8 OCT 97	1508577 61913, 1A, B	

Parcel Number	AIN	Situs Address
052050010040	213851	20463 S LOFFS BAY RD, COEUR D ALENE

Owner Information

Owner Name	PERKINS THOMAS B ETUX
Owner Address	5328 E BARWICK DR CAVE CREEK AZ 85331

Transfer Date**Document #****Deed Book/Page**

Location / Description

Tax Authority Group	249000	Current Legal Desc.	MCLEAN MEADOWS, LT 4 BLK 1 33 49N 03W
Situs Address	20463 S LOFFS BAY RD, COEUR D ALENE		
Acreage	10.5470		

Parcel Type

Property Class Code	537- Imp res rural sub
Neighborhood Code	5200 48N 5&6W; 49N 5&6W