



State of Idaho

DEPARTMENT OF WATER RESOURCES

Northern Region, 7600 Mineral Drive, Suite 100, Coeur d'Alene, Idaho 83815

Phone: (208) 762-2800 FAX: (208) 762-2819 www.idwr.idaho.gov

C.L. "BUTCH" OTTER
Governor

GARY SPACKMAN
Director

February 6, 2014

Darin Petty OR Kelly Petty
10303 N Stoneman Bluff LN
Spokane, WA 99217

Re: Coeur d'Alene-Spokane River Basin Adjudication (CSRBA) Claims No. 95-15000 and 95-15001

Dear Claimants:

Idaho Department of Water Resources (IDWR) has completed initial review of your two Internet CSRBA Claims (95-15000 & 95-15001) to provide water for a home in Bonner County. Copies of your Claims, a map, and a Well Driller's Report are enclosed.

Please contact me about the correct tax parcel for Domestic use, the correct location and completion date for your well, and the Priority Date description (# 13) on Claim 95-15001. This information is needed from you for IDWR's recommendations to the Court on your Claims.

My telephone number at the IDWR Northern Region Office is (208) 762.2816.

Respectfully,

Shaun M. Maxey
Senior Water Resource Agent
Idaho Department of Water Resources, Northern Region

Enclosures

Copies of CSRBA Claims 95-15000 & 95-15001
IDWR Map (2009 Image)
Well Driller Report 96-86-N-79

SCANNED

FEB 13 2014

* All wells are located on map.

2009 Property domestic use and

Parcel #21 owned with my parents, Herb & Jackie Alt (not listed here)

Kelly Petty
(509) 342-5360


Not the correct well report but is same date.

RECEIVED

FEB 13 2014

IDWR / NORTH

95-15000 AND 95-15001 PETTY (2009 IMAGE)



SCANNED

FEB 13 2014

DRILLER'S REPORT

to be filed with the Director, Department of Water Resources
at the completion or abandonment of the well.

POSTED

RECEIVED
FEB 13 2014
IDWR/NORTH

This report
is for Steve
and Kathy
Altmeyer.
Our report
should say
Roscoe Altmeyer
(same date,
done together)

7. WATER LEVEL

Static water level 25 feet below land surface.Flowing? ☐ Yes ☒ No G.P.M. flow _____

Artesian closed-in pressure _____ p.s.i.

Controlled by: ☐ Valve ☒ Cap ☐ PlugTemperature 60.0°F. Quality Excellent

Describe artesian or temperature zones below

8. WELL TEST DATA

☐ Pump ☐ Baller ☒ Air ☐ Other _____

Discharge G.P.M. Pumping Level Hours Pumped

50 variable 1/2 hr.


9. LITHOLOGIC LOG

Bore Diam.	Depth		Material	Water	
	From	To		Yes	No
8	0	9	Decomposed Granite	X	
9	9	18	Granite	X	
6	18	50	Broken Granite	X	

How casing drive shoe used? ☐ Yes ☒ No
Was a packer or seal used? ☐ Yes ☒ No
Perforated? ☒ Yes ☐ No
How perforated? ☐ Factory ☐ Knife ☐ Torch
Size of perforation 24 inches by 3 inches
Number From To
30 perforations 30 feet 50 feet
_____ perforations _____ feet _____ feet
_____ perforations _____ feet _____ feet
Well screen installed? ☐ Yes ☒ No
Manufacturer's name _____
Type _____ Model No. _____
Diameter _____ Slot size _____ Set from _____ feet to _____ feet
Diameter _____ Slot size _____ Set from _____ feet to _____ feet
Gravel packed? ☐ Yes ☒ No ☐ Size of gravel _____
Placed from _____ feet to _____ feet
Surface seal depth 18 Material used in seal: ☐ Cement grout
☒ Bentonite ☐ Puddling clay ☒ Cotton lumps
Sealing procedure used: ☐ Slurry pit ☐ Temp. surface casing
☒ Overbore to seal depth
Method of joining casing: ☐ Threaded ☒ Welded ☐ Solvent
Weld _____
☐ Cemented between strata
Describe access port _____

5. LOCATION OF WELL

Sketch map location must agree with written location.



Subdivision Name _____

Lot No. _____ Block No. _____

County _____

SE 1/4 SE 1/4 Sec. 21, T. 54 N., R. 3 E (W)

10.

Work started 10/22/86 finished 10/22/86

11. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were
complied with at the time the rig was removed.Firm Name Associated Well Firm No. 245Address Box 723 C.O.A. Date 10/22/86Signed by (Firm Official) Bob [Signature]and
(Operator) Robert F. Degitz