

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Inspected by			
Twp	Rge	Sec	
	1/4	1/4	1/4
Lat:	:	Long:	:

1. DRILLING PERMIT NO. 831570

Other IDWR No. D 0040007

2. OWNER:

Name James & Dottie Ginn

Address 6198 Harbor Dr

City Coeur d'Alene State ID Zip 83814

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location

N

W		E	Twp. <u>50</u> North ☒ or South ☐
			Rge. <u>4</u> East ☐ or West ☒
			Sec. <u>8</u> 1/4 SW 1/4 NW 1/4
			10 acres 40 acres 160 acres

S

Gov't lot _____ County _____

Lat: 47:41:818 Long: 116:52:157

Address of Well Site 6198 Harbor Dr

City Coeur d'Alene

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK		AMOUNT		METHOD
Material	From	To	Sacks or Pounds	
Bentonite	0	20	300	Dry Granular

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	178	250	Steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations Method _____

☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

96ft. below ground

Artesian Pressure _____ lb

Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:

- ☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal/min.	Drawdown	Pumping Level	Time
10-12			

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: Cloudy, then mostly clear

Depth first Water Encountered 73'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water				Y	N
Bore Dia	From	To	Remarks: Lithology, Water Quality & Temp.		
10"	0	12	Gravel, Sand, Silt		
	12	20	Sand, Silt, brown		
8"	20	23	Sand, Silt		
	23	29	Gravel,		
	29	47	Gravel, coarse, Cobbles		
	47	86	Sand, Gravel		
	86	101	Gravel, Boulders		
	101	107	Gravel, fine, Silt, brown		
	107	112	Basalt, vesicular 5GPM		
	112	138	Basalt, grey, medium		
	138	147	Basalt, broken 3GPM		
	147	186	Basalt, hard		
6"	186	187	Basalt, medium 6GPM		
	187	196	Basalt, medium		
	196	199	Clay, grey		

0007
D004007
is correct well
tag for well on his property
WEEKS
95-16808
N0305FL
(208) 512. 5394
WEEKS called tag
number in 9/20/14
am.

Completed Depth: 197

(Measurable)

Date: Started 3/16/05

Completed 3/21/05

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name McCarthy Drilling & Pump Inc

Firm No. 586

Firm Official [Signature]

Date 3/22/05

Supervisor or Operator _____

(Sign once if Firm Official & Operator)

Date _____

SCANNED

SEP 26 2014