

WELL DRILLER'S REPORT
77887

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat : : Long : :

1. WELL TAG NO. D5729 JAN 15 1999

Drilling Permit No: _____
Other IDWR No. 95-98-N-230 IDWR North


2. OWNER Well Number: 830

Name MCNEIL, VICTORIA

Address 4303 KINGSWAY

City ANACORTES State WA Zip 98221

3. LOCATION OF WELL by legal description
sketch map location must agree with written location



Twp. 48 ☒ North or ☐ South
Rge. 04 ☐ East or ☒ West
Sec. 35 1/4 NE 1/4 NE 1/4

Gov't Lot _____ County KOOTENAI

Lat : : Long : :

Address of Well Site HARLOW PT

City HARRISON

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement, etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Secks or Pounds	
BENTONITE	0	25	1 GALLON	VERBORE/POUR

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 81

Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	81	.250	STEEL	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

18 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:

☐ Pump ☐ Baller ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
50+ GPM		80	2 HRS

Water Temp. COLD Bottom Hole Temp SAME

Water Quality test or comments: CLOUDY

Depth first Water encountered 30'

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

				Water	
Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Y	N
8	0	20	Broken Basalt W/Clay	☐	☒
8	20	28	Clay Brown	☐	☒
8	28	36	Basalt Gravel W/Cobble	☒	☐
8	36	39	Basalt Boulder	☒	☐
8	39	45	Basalt Broken W/Clay	☒	☐
8	45	63	Basalt Gravel W/Water	☒	☐
8	63	66	Basalt W/Clay	☒	☐
8	66	81	Gravel W/Water	☒	☐
	0	0	It Cleaned up 80%	☐	☐
	0	0	Water was real Cloudy/after developme	☐	☐

Completed Depth 81' (Measurable)

Date: Started 12/31/98 Completed 1/4/99

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H2O Well Service, Inc. Firm No. 448

Firm Official [Signature] Date 1/4/99

and Supervisor or Operator [Signature] Date 1/4/99

(Sign Once if Firm Official and Operator)

(Louie Hanner)

48N 4W 35