

MAY 27 1998
3/95

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

Office Use Only
Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 1/4 1/4
Lat: _____ Long: _____

NORTHERN REGION

IDWR
D0003769

1. DRILLING PERMIT NO. 95-98-11-49

Other IDWR No. _____

2. OWNER:

Name Max Snyder

Address PO Box 35224

City Spokane State WA Zip 99223

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N
W
E
S
Twp. 48 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 35 1/4 1/4 1/4 1/4
Gov't Lot _____ County _____
Lat: _____ Long: _____
Address of Well Site Harlow Point
City Harrison
lots
(Give at least name of road + Distance to Road or Landmark)

Lt. 34.5 Blk. _____ Sub. Name _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT Sacks or Pounds	METHOD
Material	From	To		
<u>Bentonite</u>	<u>0</u>	<u>42</u>	<u>800</u>	<u>Row dry</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 76

Was drive shoe seal tested? ☒ Y ☐ N How? AK

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>12"</u>	<u>12</u>	<u>76</u>	<u>250</u>	<u>Steel</u>	☒	☐	☒	☐
<u>4"</u>	<u>-20</u>	<u>-80</u>	<u>160</u>	<u>PVC</u>	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

- ☒ Perforations Method Drill
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
<u>40</u>	<u>80</u>	<u>1/4"</u>	<u>80</u>		<u>PVC</u>	☐	☒

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

51 ft. below ground Artesian pressure N/A lb.

Depth flow encountered 78 ft. Describe access port or

control devices: cap

48N 4W 35 SWSW

FORWARD WHITE COPY TO WATER RESOURCES

11. WELL TESTS:

- ☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min	Drawdown	Pumping Level	Time
<u>60</u>			

Water Temp. Cold Bottom hole temp. _____

Water Quality test or comments: Cleaned up slowly

Depth first Water Encountered 78'

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>8"</u>	<u>0'</u>	<u>6'</u>	<u>Fill (Boulders & clay)</u>		☒
<u>8"</u>	<u>6'</u>	<u>28'</u>	<u>Basalt basalt clay & gravel</u>		☒
<u>8"</u>	<u>28'</u>	<u>38'</u>	<u>Sand, clay & boulders</u>		☒
<u>8"</u>	<u>38'</u>	<u>42'</u>	<u>Broken Basalt</u>		☒
<u>10"</u>	<u>42'</u>	<u>100'</u>	<u>Broken Basalt</u>		☒

RECEIVED

MAY 27 1998

NORTHERN REGION
IDWR

Completed Depth 80' (Measurable)

Date: Started 4-21-98 Completed 4-23-98

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Always Drilling Firm No. 570

Firm Official Stanley K. Welfe Date 4/22/98

and _____

Supervisor or Operator With [Signature] Date 4-23-98

(Sign once if Firm Official & Operator)

SCANNED

DEC 26 2017