SEP 2 4 1998

Form 238-7
11/97

NORTHERN REGION
IDWR

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

77837

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D --000 #5315
DRILLING PERMIT NO. 95-98-N-172
Other IDWR No. _____

2. OWNER:
Name GARY CAMPBELL
Address P.O. BOX 2169
City CD'A State ID Zip 83814

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

POSTED

N / W / E / S

Twp. 48 North XX or South ☐
Rge. 03 East ☐ or West XX
Sec. 15, 7100 1/4 SE 1/4 SW 1/4 (10 acres / 40 acres / 160 acres)
Gov't Lot ____ County BENEWAH
Lat: : : Long: : :
Address of Well Site THOMPSON LAKE RD.
BLUE LAKE RD. City HARRISON
PARCEL # TWP48NR03WSEC15-1.10 ACRES
Lt. _____ Blk. _____ Sub. Name _____

4. USE:
XX ☐ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply. (Replacement etc.)
XX ☐ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
XX ☐ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	39	750 pnds	poured

Was drive shoe used? XX Y ☐ N Shoe Depth(s) 39 ft
Was drive shoe seal tested? XX Y ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+1	39	250	Steel	XX	☐	XX	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
XX Perforations Method Drilled
X Screens Screen Type plastic

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
30	150	1/2		4"	plastic	☐	XX
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
60 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:
☐ Pump ☐ Bailer XX Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
Est 20	GAL. Min.		

Water Temp. Cold Bottom hole temp. Cold
Water Quality test or comments: good
Depth first Water Encounter 135 ft.

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	3	Top Soil		X
8	3	12	Broken Basalt		X
8	12	22	Gray Clay		X
8	22	35	Broken Basalt		X
8	35	39	Hard Basalt		X
6	39	135	Hard Basalt		X
6	135	150	Broken Basalt	X	

Completed Depth 150' FEET (Measurable)
Date: Started 9/12/98 Completed 9/15/98

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name PRECISION DRILLING Firm No. 0558
Firm Official Joanne D Cameron Date 9/15/98
and
Driller or Operator Joann N Cameron Date 9/15/98
(Sign once if Firm Official & Operator)

48 N 3W 15 FORWARD WHITE COPY TO WATER RESOURCES

SCANNED
JAN 04 2018