Form 238-7
7/98
Starships Consulting and Management Services

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by_____
Twp____Rge____Sec____
____1/4____1/4____1/4
Lat: : : Long: : :

JUL 17 2000

1. WELL TAG NO. D0013335
Drilling Permit No:
Other IDWR No. 765304 **IDWR/North**

2. OWNER **Well Number:** 55
Name Jane Schwartz
Address 5124 S. Sunward Drive
City Spokane State WA Zip 99223

3. LOCATION OF WELL by legal description
sketch map location must agree with written location

N / W / E / S — X

Twp. 48 ☑ North or ☐ South
Rge. 04 ☐ East or ☑ West
Sec. 20 ____ 1/4 NE 1/4 NE 1/4
Gov't Lot ____ County KOOTENAI
Lat: : : Long: : :
Address of Well Site Ben Point Road
City Coeur d'Alene
(Give at least name of road + Distance to Road or Landmark)
Lt.____ Blk. ____ Sub. Name ____

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement, etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
BENTONITE	0	18	7 sacks	overbore

Was drive shoe used? ☐ Y ☑ N Shoe Depth(s)____
Was drive shoe seal tested? ☐ Y ☐ N How?

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	2	115	.250	steel	☑	☐	☑	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
☐ Perforations Method ____
☐ Screens Screen Type ____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
70 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: ____

48N 4W 20

POSTED

11. WELL TESTS:
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
15+			1 hour

Water Temp. cold Bottom Hole Temp cold
Water Quality test or comments: clear
Depth first Water encountered 90

12. LITHOLOGIC LOG:(Describe repairs or abandonment)

Bore Diam	From	To	Remarks: Lithology, Water Quality, Temperature	Water Y	Water N
8	0	4	Topsoil	☐	☑
8	4	18	Basalt broken w/clay	☐	☑
8	18	90	Basalt broken w/clay	☐	☑
8	90	96	Basalt broken w/clay	☑	☐
8	96	101	Shale broken w/clay	☐	☑
8	101	109	Clay tan w/basalt	☐	☑
8	109	115	Basalt & hard clay	☑	☐
8	115	119	Basalt & hard clay	☑	☐
			Bottom of well is 109'	☐	☐
	109	119	Gravel packed with 3/8" washed pea gr	☐	☐

SCANNED
JAN 11 2018

Completed Depth 119 (Measurable)
Date: Started 7/7/00 Completed 7/10/00

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name H20 WellService, Inc. Firm No 448
Firm Official [signature] Date 7-12-00
and
Supervisor or Operator [signature] Date 7-11-00
(Sign Once if Firm Official and Operator)
Todd Morgan