

NOTICE OF ERROR
REPLY

RECEIVED
02/09/2018
MAR 14 2018
IDWR / NORTH

Please type or print clearly, fill out this form completely and mail.

Return this reply form to IDWR by the deadline date printed below if you want IDWR to change your recommendation or you want to let IDWR know that you agree with its recommendation.

YOUR DEADLINE FOR RETURNING A NOTICE OF ERROR REPLY IS: March 30, 2018

Water right number: 95-10664 ✓

WELCH K BAR RANCH
8865 FERNAN LAKE RD
COEUR D ALENE ID 83814
Telephone Number: 2086672371

1. Describe the portion of the proposed recommendation with which you disagree (e.g. priority date, period of use, source):

The well in the SENE-9-50N-3W was replaced by a well drilled in 4-18-91. We are using this water for the uses claimed.

2. Describe the changes you wish to make in the proposed recommendation:

That the water from new well be allowed for live stock, irrigation, + domestic use.

3. Give a brief explanation as to why you disagree with these portions:

The old well that is no longer used was approved instead of the new well.

____ I AGREE with this proposed recommendation: no changes need to be made.

DATE: 3-14-2018

SIGNATURE: Roberta A. Welch

Please print your name:

Roberta A. Welch

IDWR Regional Office, 7600 N MINERAL DR STE 100, COEUR D ALENE, ID 83815-7763, (208) 762-2800

STATE OF IDAHO
DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

State law requires that this report be filed with the Director, Department of Water Resources
within 30 days after the completion or abandonment of the well.

RECEIVED

MAR 14 2006

TYPEWRITER OR
BALLPOINT PEN

IDWR/NORTH

1. WELL OWNER

Name Howard Bobbie WelchAddress 16855 Fernan Creek RdDrilling Permit No. CDA ID 83814Water Right Permit No. 95-91-N-39

2. NATURE OF WORK

- ☒ New well ☐ Deepened ☐ Replacement
☐ Well diameter increase
☐ Abandoned (describe abandonment procedures such as materials, plug depths, etc. in lithologic log)

3. PROPOSED USE

- ☒ Domestic ☐ Irrigation ☐ Test ☐ Municipal
☐ Industrial ☐ Stock ☐ Waste Disposal or Injection
☐ Other _____ (specify type)

4. METHOD DRILLED

- ☒ Rotary ☒ Air ☐ Hydraulic ☐ Reverse rotary
☐ Cable ☐ Dug ☐ Other _____

5. WELL CONSTRUCTION

Casing schedule: ☐ Steel ☐ Concrete ☐ Other _____

Thickness	Diameter	From	To
25' inches	6' inches	2 feet	25 feet
PVC inches	4 inches	20 feet	400 feet

Was casing drive shoe used? ☒ Yes ☐ NoWas a packer or seal used? ☐ Yes ☒ NoPerforated? ☐ Yes ☒ NoHow perforated? ☐ Factory ☐ Knife ☐ Torch ☐ GunSize of perforation 3/8" drill inches by _____ inches

Number	From	To
100 perforations	300 feet	400 feet
perforations	feet	feet
perforations	feet	feet

Well screen installed? ☐ Yes ☒ No

Manufacturer's name _____

Type _____ Model No. _____

Diameter _____ Slot size _____ Set from _____ feet to _____ feet

Diameter _____ Slot size _____ Set from _____ feet to _____ feet

Gravel packed? ☐ Yes ☒ No ☐ Size of gravel _____

Placed from _____ feet to _____ feet

Surface seal depth 25' Material used in seal: ☐ Cement grout☒ Bentonite ☐ Pudding clay ☐ _____Sealing procedure used: ☐ Slurry pit ☒ Temp. surface casing☒ Overbore to seal depthMethod of joining casing: ☐ Threaded ☒ Welded ☐ Solvent


Weld _____

☐ Cemented between strata

Describe access port _____

6. LOCATION OF WELL

Sketch map location must agree with written location.



Subdivision Name _____

Lot No. _____ Block No. _____

7. WATER LEVEL

Static water level 10 feet below land surface.Flowing? ☒ Yes ☐ No G.P.M. flow 23

Artesian closed-in pressure _____ p.s.i.

Controlled by: ☐ Valve ☐ Cap ☐ PlugTemperature Cold OF. Quality good

Describe artesian or temperature zones below _____

8. WELL TEST DATA

☐ Pump ☐ Bailor ☒ Air ☐ Other _____

Discharge G.P.M.	Pumping Level	Hours Pumped
<u>23</u>	<u>385</u>	<u>1</u>

9. LITHOLOGIC LOG

Bore Diam.	Depth		Material	Water Yes No
	From	To		
8	0	21	broken shale	✓
8	21	25	shale	✓
6	25	179	shale 2 grn.	✓
6	179	183	quartz	✓
6	183	240	soft granite (b+w)	✓
6	240	400	shale	✓

10.

Work started April 19 97 finished April 23/97

11. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were
complied with at the time the rig was removed.Firm Name United Drilling Firm No. 414Address P.O. Box 2499 Date April 23/97CDA ID 83814Signed by (Firm Official) [Signature]