

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
	1/4	1/4	1/4
Lat:	:	:	Long: : :

1. WELL TAG NO. D 0046080
DRILLING PERMIT NO. 842842
Water Right or Injection Well No. _____

2. OWNER:

Name Robert & Mary White
Address 2905 Birchwood Ave
City Bellingham State WA Zip 98225-1447

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 54 North ☒ or South ☐
Rge. 3 East ☐ or West ☒
Sec. 28 1/4 NE 1/4 NE 1/4
Gov't Lot _____ 10 acres County Bonner 40 acres 160 acres

Lat: : : Long: : :

Address of Well Site Kelso Lake Rd
City Athol

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply

(Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
bentonite	0	19	200lbs	surface pipe

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 22 1/2

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	22 1/2	250	steel	☒	☐	☒	☐
4	-7	187	160	pvc	☐	☒	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method saw

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
67	87	1/8x5	20	4	pvc	☐	☒
167	187	1/8x5	20	4	pvc	☐	☒

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

24 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: cap

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
3+		185	1 1/2 hr

Water Temp. cold Bottom hole temp. _____

Water Quality test or comments: clear

Depth first Water Encounter 50

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	12	fill		
	12	18	brown clay		
	18	22 1/2	decomposed granite		
6	22 1/2	40	firm salt&pepper		
	40	100	salt&pepper granite, with decomposed seams thru-out	x	
	100	127	firm salt&pepper		
	127	130	soft salt&pepper, green granite		
	130	144	firm salt&pepper		
	144	147	soft salt&pepper	x	
	147	159	firm salt&pepper		
	159	161	soft salt&pepper		
	161	187	firm salt&pepper		

RECEIVED
OCT 19 2006
IDWR/North

Completed Depth 187ft (Measurable)

Date: Started 10-13-06 Completed 10-14-06

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Bronson Water Wells Firm No. 360

Principal Driller Clint Bronson Date 10/16/06

Driller or Operator II _____ Date _____

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.

54N 3W 26