

FIELD EXAMINATION OF CSRBA WATER RIGHT CLAIM

Claim Identification Number: 95-2197

Date of Examination: 9/21/2018

Approximate Time of Examination: 1530

IDWR Field Staff: Kaila Savage

Point of Contact: Marc Andrews

Examination Location: Gloria Andrews Property; South end of Fernan Lake
Taxlot: 50N03W160650

Purpose of Visit: Confirm acreage and GPS accurate POD location

Field Examination Notes:

I met with Marc, Gloria Andrew's son, at the property as she is in an assisted living home and was unable to accompany me. He showed me the area that is currently irrigated and agreed that the Preliminary Recommendation is accurate. He was under the impression that the Recommendation should match the licensed right regardless if it was still irrigated or not.

He took me up to the small storage pond then took me back down to the well on the other side of the property. I was able to get an accurate GPS point for the well. Water conveyance system appears to be operating as originally licensed.

Well is buried, located where the moist gravel is.



SCANNED
SEP 25 2018