

RECEIVED

NOV 16 2018

10/05/2018

DEPARTMENT OF
WATER RESOURCES

NOTICE OF ERROR
REPLY

Please type or print clearly, fill out this form completely and mail.

Return this reply form to IDWR by the deadline date printed below if you want IDWR to change your recommendation or you want to let IDWR know that you agree with its recommendation.

YOUR DEADLINE FOR RETURNING A NOTICE OF ERROR REPLY IS: November 16, 2018

Water right number: 95-16850

JAY BRANTINGHAM
3759 E EMERALD DR
HARRISON ID 83833
Telephone Number: (509) 438-6219

AMY BRANTINGHAM
3759 E EMERALD DR
HARRISON ID 83833
Telephone Number: (509) 438-6219

1. Describe the portion of the proposed recommendation with which you disagree (e.g. priority date, period of use, source):

2. Describe the changes you wish to make in the proposed recommendation:

See Attached

3. Give a brief explanation as to why you disagree with these portions:

See Attached

 I AGREE with this proposed recommendation: no changes need to be made.

DATE:

11-13-2018

SIGNATURE:

Jay Brantingham

Please print your name:

Jay Brantingham

IDWR Regional Office, 7600 N MINERAL DR STE 100, COEUR D ALENE, ID 83815-7763, (208) 762-2800

Well TAG ID
D0054220



Well TAG ID
D0061233

IDAHO DEPARTMENT
OF
WATER RESOURCES

00054220

DRILLING PERMIT I.D. TAG
DO NOT REMOVE



IDAHO DEPARTMENT OF WATER RESOURCES WELL DRILLER'S REPORT

1. WELL TAG NO. D 0054220

DRILLING PERMIT NO. 749951

Water Right or Injection Well No.



2. OWNER:

Name Burma Investors Ltd. Partnership

Address P.O. Box 19

City Powell Butte State OR Zip 97753

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 49 North ☒ or South ☐

Rge. 3 East ☐ or West ☒

Sec. 16 1/4 SE 1/4 SW 1/4

Gov't Lot 10 acres County Kootenai 20 acres 150 acres

Lat. : : Long. : :

Address of Well Site Coeur d' Alene Mountain Rd. NFR

439 City Coeur d' Alene

(Give at least name of road + Distance to Road or Landmark)

Lt. Blk. Sub. Name

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply

(Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite	0	58	8 Sacks	Dry Pour
Granular				

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 58 FT

Was drive shoe seal tested? ☐ Y ☒ N How?

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+2	58	25	Steel	☒	☐	☒	☐
4	-8	400	200	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe Length of Tailpipe

Packer ☐ Y ☐ N Type

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method Drilled 3/8" Holes

Screen Type & Method of Installation

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
348	398	3/8	150	4	PVC	☐	☒
						☐	☐
						☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

20 ft. below ground Artesian pressure lb.

Depth flow encountered 125 ft. Describe access port or control devices:

Steel Cap Welded

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
30	100%	398	1 Hour

Water Temp. Cold Bottom hole temp. Cold

Water Quality test or comments: Clear, Cold, No Smell

Depth first Water Encounter 125

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
8	0	1	Clay brown		X
8	1	10	Clay & shale mix brown		X
8	10	50	Shale brown soft		X
8	50	58	Shale blue gray medium		X
6	58	88	Shale blue gray medium		X
6	88	210	Shale gray brown soft	X	
6	210	400	Shale blue gray firm	X	

RECEIVED

DEC 13 2007

DOWN/NOVA



3125 W. Hayden Ave. Hayden, ID 83835

Office (800) 682-9641 (208) 772-7867

Completed Depth 400 FT (Measurable)

Date: Started 11-13-07 Completed 11-14-07

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name United Pump & Drilling Firm No. 636

Principal Driller and Date 11-15-07

Driller or Operator II Date


Operator I Date

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.

FORWARD WHITE COPY TO WATER RESOURCES

49N 3W 16

Application for Water Right



11/13/2018 1:41:58 PM

Points

-  Override 1
-  Override 2

 Counties


 Quarter Quarter

 Section

 Township/Range

 Idaho Outline

 Idaho Mask



Esri, HERE, Garmin, © OpenStreetMap contributors, Created by NRCS from 1:24,000 scale USGS topographic maps., Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Inspected by _____			
Twp _____	Rge _____	Sec _____	
1/4 _____		1/4 _____	
Lat: _____	:	Long: _____	:

1. WELL TAG NO. **D0061233**

DRILLING PERMIT N _____

Other IDWR No _____

2. OWNER:

Name **Sam Gatfield**

Address **pobox 1690**

City **hydebln**

State ID _____

Zip **83835**

3. LOCATION OF WELL by legal description:

N		Twp 49N	North ☒ or South ☐
Rge 03W		East ☐ or West ☒	
Sec 21		1/4 NE 1/4 NW 1/4	
		10 Ac 40 Ac 160 Ac	
Gov't Lot _____		County Kootenai	
Lat 47:34:58		Long 116:43:59	

3749 emerald drive

City **harrison**

Lot _____ Blk _____ Sub. Name (see next line) _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			Amount	Method
Material	From	To	Sacks/Lbs	
bentonite	0	39	18 sacks	dry poor

Drive Shoe Used? ☒ Y ☐ N Shoe Depth(s) _____ 40ft

Drive Shoe Seal Tested? ☐ Y ☒ N How? _____

8. CASING/LINER

Diam	From	To	Gauge	Material	Casng	Liner	Weld	Thrded
6	+1	39ft	0.250	steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length Headpipe **n/a** Length Tailpipe **n/a**

9. PERFORATIONS/SCREENS

☒ Perforations? Method **pvc**

☐ Screens? Screen Type _____

From	To	Slot	Nmbr	Diam	Material	Casng	Liner
240	280	3/8	500	3/8	pvc	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL or ARTESIAN PRESSURE

-60 ft. below ground. Artesian pressure **0** lb.

Depth flow encountered **220** ft. Describe access port or

control devices: **cap**

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pump Level	Time
13 gpm	100%	280	1hr

Water Temp. _____ cold Bottom hole temp. _____ clear

Water Quality test or comments: (below) Depth first Water Encountered **220**
clear

12. LITHOLOGIC LOG (Describe repairs or abandonment)

Bore Diam	From	To	Lithology, Water Quality and Temperature	Remarks:	
				Y	N
10	0	6	top soil	☐	☒
10	6	12	clay brown	☐	☒
10	12	39	soft shale	☐	☒
6	39	125	soft shale	☐	☒
6	125	180	gray firm shale	☐	☒
6	180	280	broken shale 13 gpm 185 to 280	☒	☐

RECEIVED

OCT 12 2012

IDWR / NORTH

Completed Dept _____ 280 (Measurable)

Date: Started **10/3/2012** Completed **10/4/2012**

13. DRILLERS CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name **United Drilling Inc.**

Firm No **414**

Firm Official and

Timothy R. Volking pvc.

Date **10/10/2012**

Supervisor or Operator **Timothy R. Volking**

Date **10/10/2012**

49N 03W 21

Parcel Polygon: 127925

Serial 127925

LRSN 65933

PID 49N03W-21-2600

Name BRANTINGHAM, JAY

Legal TAX #22116 [IN NE-NW]

SA_SW Y

[Zoom to](#)