

FIELD EXAMINATION OF CSRBA WATER RIGHT CLAIM

Claim Identification Number: 95-16503

Date of Examination: 11/07/2018

Approximate Time of Examination: 1100

IDWR Field Staff: Kaila Savage

Point of Contact: Terry Harings

Examination Location: Twin Lakes, Idaho area

Purpose of Visit: Locate accurate POD and determine if other users are still on system. Locate lines. Exterior and Interior for all lots? Any of the lots on surface water; the two lots down the road.

Field Examination Notes:

Michael Strong is the claimant for 95-16503, but he doesn't maintain the system and doesn't know the location of the POD, so he had Terry Harings show me the system.

- This system is no longer for interior and exterior as previously decreed, it is strictly exterior
- No one is certain on which homes are still on the system.
- In the spring when they see a wet spot surface, they fix it and move on to the next. This is the only way to determine the location of lines.
- There are no pumps in the lake for surface water.
- This area is also served by North Kootenai Water District
- This system is gravity flow with no pump in the stream (Figure 1). There is a storage shed (Figure 2) downstream approximately 200 feet from POD

GPS Coordinates of the POD: 47°51.483'N 116°52.313W

Storage Shed GPS Coordinates: 47°51.493'N 116°52.266'W



Figure 1. POD



Figure 2. Storage shed 200 feet downstream