RECEIVED
Form 238-7
3/95
SEP 24 1997
POSTED
NORTHERN REGION
IDWR

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

097162

Office Use Only
Inspected by TDK
Twp____ Rge____ Sec____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. D0003276 - - -
Other IDWR No. 96-97-N-1660

2. OWNER:
Name Howard Bronson
Address P.O.Box 1
City Spirit Lake State ID Zip 83869

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 54 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 24, ____ 1/4 SW (10 acres) 1/4 SW (40 acres) 1/4 (160 acres)
Gov't Lot ____ County Bonner
Lat: : : Long: : :
Address of Well Site Hwy 41 Mile Post 23
City Spirit Lake
(Give at least name of road + Distance to Road or Landmark)
Lt.____ Blk.____ Sub. Name____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
bentonite	0	18	8	overbore

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s)____
Was drive shoe seal tested? ☐ Y ☐ N How?____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6	+1	158	250	steel	☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe____ Length of Tailpipe____

9. PERFORATIONS/SCREENS
☐ Perforations Method____
☒ Screens Screen Type stainless (telescoping)

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
158	163	20				☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
110 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: cap

11. WELL TESTS:
☐ Pump ☐ Bailer ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
20		160	4hrs

Water Temp. ____ Bottom hole temp. ____
Water Quality test or comments: ____
Depth first Water Encountered ____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	70	sand&peagravel		
6	70	76	large gravel		
	76	163	peagravel&sand	X	

Completed Depth 163ft (Measurable)
Date: Started 9-2-97 Completed 9-2-97

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Bronson Water Wells Firm No. 360
Firm Official Christ Bronson Date 9-10-97
and
Supervisor or Operator____ Date____
(Sign once if Firm Official & Operator)

SWSW 24 54N 5W

FORWARD WHITE COPY TO WATER RESOURCES