RECEIVED
JUL 19 2001
IDWR-North

RECEIVED
AUG - 1 2001
IDWR-North

Form 238-7
11/97

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 0017317
DRILLING PERMIT NO. - - - -
Other IDWR No. 769249

WELL TESTS: ☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
4½ = 5 gpm			

Water Temp. 54° Bottom hole temp. _____
Water Quality test or comments: Good
Depth first Water Encounter 320

2. OWNER:
Name Craig Knott
Address 208 Linden Court
City Pittsburg State ID Zip 83855

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

POSTED

N / W / E / S — X

Twp. 41 North ☑ or South ☐
Rge. 5 East ☐ or West ☑
Sec. 34, ____ 1/4 (10 acres) NW 1/4 (40 acres) NE 1/4 (160 acres)
Gov't Lot ____ County Latah
Lat: : : Long: : :
Address of Well Site 4 miles south of Viola
(Give at least name of road + Distance to Road or Landmark)
City Viola

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	60	12 bags	Dry

Was drive shoe used? ☑ Y ☐ N Shoe Depth(s) 98 ft
Was drive shoe seal tested? ☑ Y ☐ N How? air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	98	250	steel	☑	☐	☑	☐
4½"	-80	400	160	PVC	☐	☑	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
☑ Perforations Method Circular Saw
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
360	400	1/8"	98	4½	PVC	☐	☑
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
145 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: Top of Well

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	2	dirt		
	2	11	clay		
	11	88	soft brown decomposed granit		
	88	100	med granit gray		
6	100	350	med soft granit		
	350	362	brown granit soft	✓	
	362	400	gray med soft granit	✓	

RECEIVED
SEP 14 2001
Department of Water Resources

Completed Depth 400 ft (Measurable)
Date: Started 6/1/01 Completed 6/3/01

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Wilcomb Drilling Firm No. 125
Firm Official Wm Wilcomb Date 6/14/01
and
Driller or Operator Wm Wilcomb Date 6/14/01
(Sign once if Firm Official & Operator)

41 N 5 W 34

FORWARD WHITE COPY TO WATER RESOURCES