

WELL DRILLER'S REPORT

1. WELL TAG NO. D 0040687
DRILLING PERMIT NO. 836118
Water Right or Injection Well No. _____

2. OWNER:
Name Delford Come
Address 1007 Bear Cr Rd
City Princeton State ID Zip 83857

3. LOCATION OF WELL by legal description:
You must provide address or Lot, Blk, Sub. or Directions to well.
Twp. 41 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 2 1/4 NE 1/4 NE 1/4
Gov't Lot _____ County Latah
Lat: _____ Long: _____
Address of Well Site Cumby mill site
City Princeton
(Give at least name of road - Distance to Road or Landmark)
Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
<u>Bentonite</u>	<u>0</u>	<u>25</u>	<u>Chgs</u>	<u>Dry</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 106 ft
Was drive shoe seal tested? ☒ Y ☐ N How? dry

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>8"</u>	<u>+2</u>	<u>106</u>	<u>250</u>	<u>steel</u>	☒	☐	☒	☐
<u>6"</u>	<u>100</u>	<u>180</u>	<u>160</u>	<u>PVC</u>	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____
Packer ☐ Y ☐ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method saw cut
Screen Type & Method of installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
<u>-140</u>	<u>180</u>	<u>1/8X3</u>	<u>100</u>	<u>6"</u>	<u>PVC</u>	☐	☒

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

22 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: top of well
41 N 4 W 2

Office Use Only	
Well ID No.	_____
Inspected by	_____
Twp _____ Rge _____ Sec _____	_____
1/4 _____ 1/4 _____ 1/4 _____	_____
Lat: _____	Long: _____

12. WELL TESTS:

☐ Pump	☐ Bailor	☒ Air	☐ Flowing Artesian
Yield gal./min.	Drawdown	Pumping Level	Time
<u>30 gpm</u>			

Water Temp. 54° Bottom hole temp. 54°

Water Quality test or comments: Good

Depth first Water Encounter 160

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>10</u>	<u>0</u>	<u>2</u>	<u>dirt</u>		
	<u>2</u>	<u>20</u>	<u>clay</u>		
	<u>20</u>	<u>93</u>	<u>sand + gravel</u>		
	<u>93</u>	<u>106</u>	<u>clay shale</u>		
	<u>106</u>	<u>180</u>	<u>very broken basalt started to get water at 160 ft</u>		

RECEIVED
OCT 04 2005
IDWR/North

Completed Depth 180 ft (Measurable)
Date: Started 9/13/05 Completed 9/15/05

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Uhlir & Drill Firm No. 125
Principal Driller Tom Uhlir Date 9/25/05
and _____ Date _____
Driller or Operator II _____ Date _____
Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.