Form 238-7
6/07

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

1. WELL TAG NO. D D0067713
Drilling Permit No. 873046
Water right or injection well #

2. OWNER:
Name Heath Morphis #2
Address 12260 W. Parkway Dr.
City Post Falls State ID Zip 83854

3.WELL LOCATION:
Twp. 50 North ☒ or South ☐ Rge. 05 East ☐ or West ☒
Sec. 17 ____ 10 acres 1/4 SE 40 acres 1/4 SW 160 acres 1/4
Gov't Lot ____ County Kootenai
Lat. 47 ° 40 : 373 (Deg. and Decimal minutes)
Long. 116 ° 59 : 767 (Deg. and Decimal minutes)
Address of Well Site 3689 Carpenter Loop
(Give at least name of road + Distance to Road or Landmark) City Post Falls, Id 83854
Lot. ____ Blk. ____ Sub. Name

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation ☐ Thermal ☐ Injection
☐ Other

5. TYPE OF WORK:
☒ New well ☐ Replacement well ☐ Modify existing well
☐ Abandonment ☐ Other

6. DRILL METHOD:
☒ Air Rotary ☐ Mud Rotary ☐ Cable ☐ Other

7. SEALING PROCEDURES:

Seal material	From (ft)	To (ft)	Quantity (lbs or ft³)	Placement method/procedure
Bentanite	0	38	2200	Over bore

8. CASING/LINER:

Diameter (nominal)	From (ft)	To (ft)	Gauge/ Schedule	Material	Casing	Liner	Threaded	Welded
6	+2	-38	250	Steel	☒	☐	☐	☒
4	-10	-340	200	Pvc	☐	☒	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Was drive shoe used? ☐ Y ☐ N Shoe Depth(s)

9. PERFORATIONS/SCREENS:
Perforations ☒ Y ☐ N Method Skillsaw
Manufactured screen ☐ Y ☒ N Type
Method of installation

From (ft)	To (ft)	Slot size	Number/ft	Diameter (nominal)	Material	Gauge or Schedule
320	340	48	1/4 x 8	4	Pvc	.200

Length of Headpipe ____ Length of Tailpipe ____
Packer ☐ Y ☒ N Type

10.FILTER PACK:

Filter Material	From (ft)	To (ft)	Quantity (lbs or ft³)	Placement method

11. FLOWING ARTESIAN:
Flowing Artesian? ☐ Y ☒ N Artesian Pressure (PSIG)
Describe control device

12. STATIC WATER LEVEL and WELL TESTS:
Depth first water encountered (ft) 100 Static water level (ft) 100
Water temp. (°F) Cold Bottom hole temp. (°F) Cold
Describe access port Welded Steel Cap

Well test:

Drawdown (feet)	Discharge or yield (gpm)	Test duration (minutes)
	15	1 hr.

Test method:

Pump	Bailer	Air	Flowing artesian
☐	☐	☒	☐
☐	☐	☐	☐

Water quality test or comments:

13. LITHOLOGIC LOG and/or repairs or abandonment:

Bore Dia. (in)	From (ft)	To (ft)	Remarks, lithology or description of repairs or abandonment, water temp.	Water Y	Water N
10	0	3	Top Soil		X
10	3	24	Granite Decomposed		X
10	24	38	Granite Grey Med		X
6	38	45	Granite Grey Med		X
6	45	57	Granite Rose Med		X
6	57	80	Granite Grey Green		X
6	80	285	Granite Grey		X
6	285	295	Granite Rose 1GPM	X	
6	295	310	Granite Grey		X
6	310	340	Granite Grey Green	X	

RECEIVED
OCT 06 2014
IDWR / NORTH

Completed Depth (Measurable): 340
Date Started: Aug 26, 2014 Date Completed: Aug 27, 2014

14. DRILLER'S CERTIFICATION:
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name H2O Well Service Inc. Co. No. 448
*Principal Driller Tom Rumler Date 9-3-14
*Driller Jon McFarlen Date 9-3-14
*Operator II Date
Operator I Date

*** Signature of Principal Driller and rig operator are required.**