RECEIVED

FEB 08 2000

IDWR/North

091782

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

POSTED

NO PERF

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : Long: : :

1. WELL TAG NO. D 0010299
DRILLING PERMIT NO. _____
Other IDWR No. 748030

2. OWNER:
Name Dale Rose
Address Box 532
City Petersburg State AL Zip 99833

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 42 North ☑ or South ☐
Rge. 3 East ☐ or West ☑
Sec. 35, 1/4 SW (10 acres) 1/4 SE (40 acres) 1/4 (160 acres)
Gov't Lot ____ County Latah
Lat: : : Long: : :
Address of Well Site Next To 4601 Hwy 6
City Harvard
(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
bentonite	0	56	300 lbs	dry

Was drive shoe used? ☑ Y ☐ N Shoe Depth(s) _____
Was drive shoe seal tested? ☐ Y ☑ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8	+1	56	250	Steel	☑	☐	☑	☐
6	-9	178		PVC	☐	☑	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS
Perforations ☑ Method Saw
Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
138	178	10x8				☐	☑
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
61 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: _____

11. WELL TESTS:
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
approx. 7			

Water Temp. _____ Bottom hole temp. _____
Water Quality test or comments: _____
Depth first Water Encounter 78

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10	0	22	overburden		✓
10	22	48	soft granit		✓
10	48	56	granit firm		✓
8	56	79	granit, firm	✓	✓ wtrbrg
8	79	85	clay		✓
8	85	123	soft granit		✓
8	123	131	granit firm		✓
8	131	178	Fract. granit	✓	

Completed Depth 178 (Measurable)
Date: Started 10/9/99 Completed 10/12/99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Witt Well Drilling Firm No. 58
Firm Official Roger Witt Date 12/14/99
and
Driller or Operator _____ Date _____
(Sign once if Firm Official & Operator)

42N 3W 35 FORWARD WHITE COPY TO WATER RESOURCES