

Location Corrected by IDWR To:
T39N R05W Sec. 22 SWNESE
By: mciscell 2013-09-24

Form 238-7

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

1. WELL TAG NO. D0059589
DRILLING PERMIT NO. 8162422
Water Right or Injection Well#
2. OWNER:
Name: Candice Claiborn
Address: 210 N. Van Buren
City: Moscow State: Idaho Zip: 83843

3. LOCATION OF WELL by legal description

Twp. 36 North ☒ Rge. 5 West ☒
Sec. 22 N/E 1/4 S/E 1/4
40 acres 160 acres

Gov't Lot County Latah
Lat. 46° 42' 371" Deg. And Decimal min.
Long. 116° 56' 458" Deg. And Decimal min.

Address of well site: 2 mile on Lenville Rd.

City: Moscow

Lot Blk. Sub. Name

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation ☐ Injection

5. TYPE OF WORK:

☒ New Well ☐ Replacement ☐ Modify existing ☐ Abandonment ☐ Other

6. DRILL METHOD: Air Rotary

7. SEALING PROCEDURES:

Seal Material	From	To (ft)	Quantity (lbs. or ft.)	Placement method/procedure
Bentonite	0	38	950	Pour

8. CASING/LINER:

Depth (ft)	From	To	Gauge/Schedule	Material	Coating	Liner	Threaded	Welded	Glued
6"	+2	193	250	Steel	X			X	
4"	-5	495	160	PVC		X			X

Was drive shoe used? YES

Shoe Depth 193

9. PERFORATIONS/SCREENS

Perforations ☒ Yes ☐ No Method Drill
Manufactured screen ☐ Yes ☒ No Type

Method of installation:

From	To	Slot Size	Number	Diam.	Material	Gauge or Schedule
480	460	1"	16	4"	PVC	160 liner
440	420	1"	16	4"	PVC	160 liner
300	280	1"	16	4"	PVC	160 liner

Length of Headpipe

Length of tailpipe:

Packer ☐ Yes ☒ No Type:

10. FILTER PACK

Filter Material	From	To	Filter Volume	Placement Method
NONE				

11. FLOWING ARTESIAN:

Flowing artesian ☐ Yes ☒ No Artesian Pressure (PSIG)
Describe control device: Cap

12. STATIC WATER LEVEL AND WELL TESTS:

Depth first water encountered (ft) 285 Static water level: 124
Water temp. 50 deg. Bottom hole temp.
Describe access port: cap

Well Test:

Test Method:

Drawdown (feet)	Discharge or yield	Test Duration	Pump	Ballast	Air	Flowing Artesian
Est. 5 gal.	3 hrs.		☐	☐	☒	☐

Water quality test or comments:

Good, clear, no odor

13. LITHOLOGIC LOG and/or repairs or abandonment:

Bore Dia.	From (ft.)	To (ft.)	Remarks, lithology or description of repairs or abandonment	Water	
				Y	N
10	0	1	Top Soil		
10	1	52	Brown Clay		
8	52	79	Pink Clay		
8	79	110	Decomposed Brown & White Granite		
8	110	120	Brown Sandy Granite		
8	120	134	Brown Clay		
8	134	165	Brown & White Soft Granite		
8	165	177	Brown Hard Granite		
8	177	230	Brown Granite, Medium Hard		
6	230	285	Gray and Brown Granite	X	
6	285	360	Gray Granite, Hard		
6	360	392	Medium Hard Gray Granite		
6	392	410	Hard Gray Granite		
6	410	426	Medium Hard Gray Granite		
6	426	440	Medium Hard Brown/Gray Granite		
6	440	452	Hard Brown/Gray Granite		
6	452	482	Medium Hard Brown/Gray Granite	X	
6	482	500	Hard Gray Granite		

RECEIVED
18 2011

Completed Date: 11/3/2011
Data Started: 10/28/2011
Data Completed: 11/3/2011

14. DRILLER'S CERTIFICATION:

Company Name: All Ways Drilling, Inc. Co. No. 510
Principal Driller Stanley K Wolfe Date 11/15/11
Driller Stanley K Wolfe Date
Operator II Date

*Signature of Principal Driller and rig operator are required.

Stanley K Wolfe

11/15/11

36N 05W 22