

IDAHO DEPARTMENT OF WATER RESOURCES  
WELL DRILLER'S REPORT

Location Corrected by IDWR To:

T41N R03W Sec. 30 SESENE

By: mciscell 2013-10-03

1. WELL TAG NO. D 0056654

DRILLING PERMIT NO. \_\_\_\_\_

Water Right or Injection Well No. \_\_\_\_\_

## 2. OWNER:

Name Martha Lindahl & John ReedAddress 1109 Chaney Rd.City Viola State ID Zip 83872

## 3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 41N North ☐ or South ☐Rge. 3W East ☐ or West ☐Sec. 30 1/4 NE 1/4 SE 1/4Gov't Lot \_\_\_\_\_ County LatahLat: 46:52:309 Long: 116:45:498Address of Well Site 1138 Grange Park RdCity Princeton

(Give at least name of road + Distance to Road or Landmark)

Lt. \_\_\_\_\_ Blk. \_\_\_\_\_ Sub. Name \_\_\_\_\_

## 4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation  
☐ Thermal ☐ Injection ☐ Other \_\_\_\_\_

## 5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other \_\_\_\_\_

## 6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other \_\_\_\_\_

## 7. SEALING PROCEDURES

| Seal Material    | From     | To        | Weight / Volume | Seal Placement Method |
|------------------|----------|-----------|-----------------|-----------------------|
| <u>Bentonite</u> | <u>0</u> | <u>30</u> | <u>350 lbs</u>  | <u>top pour</u>       |

Was drive shoe used? ☒ ☐ N Shoe Depth(s) 38Was drive shoe seal tested? ☒ ☐ N How? air

## 8. CASING/LINER:

| Diameter      | From       | To         | Gauge      | Material     | Casing                              | Liner                               | Welded                              | Threaded                 |
|---------------|------------|------------|------------|--------------|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| <u>6"</u>     | <u>+2</u>  | <u>30</u>  | <u>250</u> | <u>Steel</u> | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| <u>4 1/2"</u> | <u>-35</u> | <u>375</u> | <u>160</u> | <u>PVC</u>   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |

Length of Headpipe \_\_\_\_\_ Length of Tailpipe \_\_\_\_\_

Packer ☐ Y ☒ N Type \_\_\_\_\_

## 9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method skill sawScreen Type & Method of Installation perforations

| From       | To         | Slot Size      | Number     | Diameter     | Material   | Casing                   | Liner                               |
|------------|------------|----------------|------------|--------------|------------|--------------------------|-------------------------------------|
| <u>335</u> | <u>375</u> | <u>1/8 x 4</u> | <u>150</u> | <u>4 1/2</u> | <u>PVC</u> | <input type="checkbox"/> | <input checked="" type="checkbox"/> |

## 10. FILTER PACK

| Filter Material | From | To | Weight / Volume | Placement Method |
|-----------------|------|----|-----------------|------------------|
|                 |      |    |                 |                  |

## 11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

56 ft. below ground Artesian pressure \_\_\_\_\_ lb.Depth flow encountered 276 ft. Describe access port or control devices: \_\_\_\_\_

## 12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

| Yield gal./min. | Drawdown | Pumping Level | Time        |
|-----------------|----------|---------------|-------------|
| <u>16 gpm</u>   |          |               | <u>1 hr</u> |

Water Temp. 43° Bottom hole temp. \_\_\_\_\_Water Quality test or comments: goodDepth first Water Encounter 276

## 13. LITHOLOGIC LOG: (Describe repairs or abandonment)

| Bore Dia. | From | To  | Remarks: Lithology, Water Quality & Temperature | Water |
|-----------|------|-----|-------------------------------------------------|-------|
| 10"       | 0    | 11  | Clay                                            | Y     |
| 10"       | 11   | 38  | md hrd granite                                  | Y     |
| 6"        | 38   | 276 | md hrd granite                                  | Y     |
| 6"        | 276  | 287 | sft granite                                     | Y     |
| 6"        | 287  | 309 | md hrd granite                                  | Y     |
| 6"        | 309  | 321 | sft granite                                     | Y     |
| 6"        | 321  | 340 | md hrd granite                                  | Y     |
| 6"        | 340  | 372 | sft granite                                     | Y     |
| 6"        | 372  | 375 | md hrd granite                                  | Y     |

RECEIVED

SEP 01 2009

IDWR/North

Completed Depth 375 (Measurable)Date: Started 8/3/09 Completed 8/5/09

## 14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Brett Uwenkott Drilling Firm No. 709Principal Driller Brett Uwenkott Date 8/29/09and Driller or Operator II Marie January Date 8/29/09

Operator I \_\_\_\_\_ Date \_\_\_\_\_

Principal Driller and Rig Operator Required.  
Operator I must have signature of Driller/Operator II.