

RECEIVED

Form 238-7

3/95

JUL 13 1998

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

77454

Office Use Only

Inspected by _____
Twp _____ Rge _____ Sec _____
1/4 _____ 1/4 _____ 1/4 _____
Lat: _____ Long: _____

NORTHERN REGION

1. DRILLING PERMIT NO.

Other IDWR No. 87-98-N-24 3911

2. OWNER:


Name Paul & Bonnie Oxford

Address _____

City Pullman State Idaho Zip 99163

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.



Twp. 40 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 17 SW 1/4 NE 1/4 1/4
Gov't Lot _____ County _____
Lat: _____ Long: _____
Address of Well Site 1/4 mile bearing Rd.
City Moscow

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT		METHOD
Material	From	To	Sacks or Pounds		
<u>bentonite</u>	<u>0</u>	<u>50</u>	<u>200 lbs</u>		<u>dry</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>8</u>	<u>+</u>	<u>1</u>	<u>50</u>	<u>250</u>	<u>Steel</u>	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

93 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

40 N 5 W 17

11. WELL TESTS:

☐ Pump ☐ Bailor

☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
<u>approx. 2</u>		<u>265</u>	<u>3 min.</u>

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encountered 240

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water	Y	N
<u>6</u>	<u>0</u>	<u>5</u>	<u>overburden</u>			
<u>10</u>	<u>5</u>	<u>38</u>	<u>granit, soft</u>			
<u>10</u>	<u>38</u>	<u>50</u>	<u>granit, firm</u>			
<u>8</u>	<u>50</u>	<u>77</u>	<u>granit, firm</u>			
<u>8</u>	<u>77</u>	<u>80</u>	<u>granit, soft</u>			
<u>8</u>	<u>80</u>	<u>93</u>	<u>granit, firm</u>			
<u>8</u>	<u>93</u>	<u>96</u>	<u>granit, hard</u>			
<u>8</u>	<u>96</u>	<u>115</u>	<u>granit, firm</u>			
<u>8</u>	<u>115</u>	<u>119</u>	<u>Fract. granit</u>			
<u>8</u>	<u>119</u>	<u>122</u>	<u>granit, firm</u>			
<u>8</u>	<u>122</u>	<u>133</u>	<u>Fract. granit</u>			
<u>8</u>	<u>133</u>	<u>138</u>	<u>granit, firm</u>			
<u>8</u>	<u>138</u>	<u>145</u>	<u>Fract. granit</u>			
<u>8</u>	<u>145</u>	<u>158</u>	<u>granit, firm</u>			
<u>8</u>	<u>158</u>	<u>165</u>	<u>Fract. granit</u>			
<u>8</u>	<u>165</u>	<u>175</u>	<u>granit, firm</u>			
<u>8</u>	<u>175</u>	<u>186</u>	<u>Fract. granit</u>			
<u>8</u>	<u>186</u>	<u>209</u>	<u>granit, firm</u>			
<u>8</u>	<u>209</u>	<u>231</u>	<u>Fract. granit</u>			
<u>8</u>	<u>231</u>	<u>240</u>	<u>granit, firm</u>			
<u>8</u>	<u>240</u>	<u>254</u>	<u>Fract. granit</u>			
<u>8</u>	<u>254</u>	<u>260</u>	<u>granit, firm</u>			
<u>8</u>	<u>260</u>	<u>262</u>	<u>Fract. granit</u>			
<u>8</u>	<u>262</u>	<u>270</u>	<u>granit, firm</u>			

Completed Depth 270 (Measurable)

Date: Started 6/25/98 Completed 6/26/98

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Witt Well Drilling Firm No. 58

Firm Official Roger Witt Date 6/30/98

and _____

Supervisor or Operator _____ Date _____

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES