RECEIVED
DEC 23 1999
IDWR/North

Form 238-7
3/95

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

0764335

Office Use Only
Inspected by _____
Twp ____ Rge ____ Sec ____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 0001057I
Other IDWR No. 87-99-N-29

2. OWNER:
Name LORI ANN M & HEATHER
Address 1500 ROCK CREEK RD
City POTLATCH State ID Zip 83855

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

POSTED

Twp. 41 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 17 ____ 1/4 SW 1/4 NW 1/4
Gov't Lot ____ County LATAH
Lat: : : Long: : :
Address of Well Site EAST ROCK CREEK RD POTLATCH
City POTLATCH
(Give at least name of road + Distance to Road or Landmark)

Lt. ____ Blk. ____ Sub. Name ____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	20	3	DRY

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 20
Was drive shoe seal tested? ☒ Y ☐ N How? 300 PSI

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8	+1	20	250	steel	☐	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
☒ Perforations Method SAW
☐ Screens Screen Type ____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
45	105	1/8 X 12	90	6"	PVC	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
33 ft. below ground Artesian pressure ____ lb.
Depth flow encountered ____ ft. Describe access port or control devices: ____

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
4		85	1 HR

Water Temp. 55° Bottom hole temp. ____
Water Quality test or comments: ____
Depth first Water Encountered 95

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
14	0	1	SOIL		
14	1	4	CLAY		
14	4	20	ARGILLITE		
8	20	38	ARGILLITE		
	38	41	ARGILLITE FRACTURED		
	41	62	ARGILLITE SOFT		
	62	74	ARGILLITE FRAC		
	74	92	ARGILLITE SOFT	X	
	92	105	ARGILLITE		

Completed Depth 105 (Measurable)
Date: Started 10-11-99 Completed 10-12-99

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the well was drilled.

McPHERSON & WRIGHT DRILLING
Firm Name 2246 Burrell Lewiston, Idaho 83501 Firm No. 0376
Firm Official (208) 743-7295 Date 12/21/99
and
Supervisor or Operator [signature] Date 12/21/99
(Sign once if Firm Official & Operator)

41 N 4 W 17

FORWARD WHITE COPY TO WATER RESOURCES