

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

1. WELL TAG NO. D 0028841DRILLING PERMIT NO. 823758

Water Right or Injection Well No. _____

2. OWNER:

Name Bruce Kennon
Address PO Box 74
City Princeton State ID Zip 83857

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 41 North ☒ or South ☐
Rge. 4 East ☐ or West ☒
Sec. 3 1/4 SW 1/4 SW 1/4
Gov't Lot _____ County LatahLat: _____ Long: _____
Address of Well Site 1/2 mile north of
City Princeton

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
<u>Bentonite</u>	<u>0</u>	<u>50</u>	<u>8 bags</u>	<u>Aug</u>

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 260Was drive shoe seal tested? ☒ Y ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6" +2</u>	<u>25</u>	<u>8250</u>	<u>steel</u>		☒	☐	☒	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method _____

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

50 ft. below ground Artesian pressure _____ lb.
Depth flow entered _____ ft. Describe access port or control devices: _____

41 N 4W 3

12. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
<u>25 gpm</u>			

Water Temp. 54.0Bottom hole temp. 54.0Water Quality test or comments: goodDepth first Water Encounter 240

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>10</u>	<u>0</u>	<u>2</u>	<u>dirt</u>		
<u>2</u>	<u>25</u>	<u>30</u>	<u>red clay</u>		
<u>8</u>	<u>25</u>	<u>30</u>	<u>red clay</u>		
<u>80</u>	<u>83</u>	<u>83</u>	<u>some gravel</u>		
<u>83</u>	<u>230</u>	<u>230</u>	<u>red clay</u>		
<u>230</u>	<u>280</u>	<u>280</u>	<u>soft shale to harder shale still not real hard</u>		

Completed Depth 280 ft (Measurable)Date: Started 8/20/04 Completed 8/24/04

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Uhlenkott Firm No. 125Principal Driller Wm Uhlenkott Date 08/18/04

and Driller or Operator II _____ Date _____

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator
8/29/2020