

IN THE DISTRICT COURT OF THE FIFTH JUDICIAL DISTRICT OF THE STATE OF IDAHO, IN AND FOR THE COUNTY OF  
TWIN FALLS

IN RE THE GENERAL ADJUDICATION OF RIGHTS TO  
THE USE OF WATER FROM THE PALOUSE RIVER  
BASIN WATER SYSTEM.

CIVIL CASE NUMBER : 59576

Ident. Number: ~~87-11591~~ 87-10024

Date Received: 8/22/2019

Receipt No: T107517

Received By:

RECEIVED

JUL 27 2020

IDWR/NORTH

AMENDED

NOTICE OF CLAIM TO A WATER RIGHT ACQUIRED  
UNDER STATE LAW

1. Name of Claimant(s)

RENAISSANCE PROPERTIES Phone: (208) 610-4078  
LLC

1651 CARMICHAEL RD  
MOSCOW ID 83843

2. Date of Priority: 5/2/2003

3. Source: GROUND WATER Tributary to:

4. Point of Diversion:

| Township | Range | Section | 1/4 of 1/4 of 1/4 | Lot | County | Type |
|----------|-------|---------|-------------------|-----|--------|------|
| 39N      | 05W   | 16      | NW SE             |     | LATAH  |      |

5. Description of diverting works:

6. Water is used for the following purposes:

| Purpose   | From To   | C.F.S. | (or) A.F.A       |
|-----------|-----------|--------|------------------|
| MUNICIPAL | 1/1 12/31 | 0.08   | <del>0</del> N/A |

7. Total Quantity Appropriated is: 0.08 C.F.S. and/or 0 A.F.A

8. Non-irrigation uses:

9. Place of use:

| Township | Range | Section | 1/4 of 1/4       | Lot              | Use           | Acres |
|----------|-------|---------|------------------|------------------|---------------|-------|
| 39N      | 05W   | 16      | SW SE            | <del>10-14</del> | MUNICIPAL     |       |
|          |       |         | <del>SW</del> SE | <del>10-14</del> | MUNICIPAL     |       |
|          |       |         | NW               |                  |               |       |
|          |       |         |                  |                  | Section Acres |       |
|          |       |         |                  |                  | Total Acres   |       |

10. Place of use in counties: LATAH

11. Do you own the property listed above as place of use? Yes

12. Other Water Rights Used:

13. Remarks:

Priority date description:

87-11591

9/3/2019

SCANNED

JUL 27 2020

Description of use: Water Use

Description

MUNICIPAL

RV Park

14. Basis of Claim: ~~Beneficial Use~~ License

15. Signature(s)

For Individuals: I/We do solemnly swear or affirm under penalty or perjury that the statements contained in the foregoing document are true and correct.

Signature of Claimant(s): \_\_\_\_\_ Date: \_\_\_\_\_

\_\_\_\_\_  
Date: \_\_\_\_\_

For Organizations: I do solemnly swear or affirm under penalty or perjury that I am

OWNER of RENAISSANCE PROPERTIES  
Title Organization

That I have signed the foregoing document in the space below as

OWNER of RENAISSANCE PROPERTIES  
Title Organization

and that the statements contained in the foregoing document are true and correct.

Signature of Authorized Agent [Signature] Date: 7/27/2020

Title and Organization DANIEL P MACK

Please print name



NWSE

NESE

16

39N05W

87

well

SWSE

SESE

SCANNED  
JUL 27 2020

WELL DRILLER'S REPORT

RECEIVED

MAY 22 2003

Office Use Only  
Well ID No. \_\_\_\_\_  
Inspected by \_\_\_\_\_  
Twp \_\_\_\_\_ Rge \_\_\_\_\_ Sec \_\_\_\_\_  
1/4 1/4 1/4  
Lat: \_\_\_\_\_ Long: \_\_\_\_\_

1. WELL TAG NO. D 00 28197  
DRILLING PERMIT NO. 796063  
Water Right or Injection Well No. \_\_\_\_\_

2. OWNER:

Name DAN Mack  
Address 676 Pullman Rd  
City MOSCOW State ID Zip 83843

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 39 North ☒ or South ☐  
Rge. 5 East ☐ or West ☒  
Sec. 16 1/4 SW 1/4 SE 1/4  
Gov't Lot \_\_\_\_\_ County LATAH

Lat: \_\_\_\_\_ Long: \_\_\_\_\_  
Address of Well Site 2 miles of Moscow  
City MOSCOW

Lt. \_\_\_\_\_ Blk. \_\_\_\_\_ Sub. Name \_\_\_\_\_

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation  
☐ Thermal ☐ Injection ☒ Other Trailer Park

5. TYPE OF WORK check all that apply (Replacement etc.)  
☒ New Well ☐ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

| Seal Material | From | To  | Weight / Volume | Seal Placement Method |
|---------------|------|-----|-----------------|-----------------------|
| Cement Grout  | 0    | 110 | 36 BAGS         | Pressure Grout        |

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 110'  
Was drive shoe seal tested? ☒ Y ☐ N How? Air Pressure

8. CASING/LINER:

| Diameter | From | To   | Gauge | Material | Casing                              | Liner                    | Welded                              | Threaded                 |
|----------|------|------|-------|----------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 8"       | +5   | -120 | .332  | Steel    | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Length of Headpipe \_\_\_\_\_ Length of Tailpipe \_\_\_\_\_  
Packer ☐ Y ☒ N Type \_\_\_\_\_

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method \_\_\_\_\_

Screen Type & Method of Installation \_\_\_\_\_

| From | To | Slot Size | Number | Diameter | Material | Casing                   | Liner                    |
|------|----|-----------|--------|----------|----------|--------------------------|--------------------------|
|      |    |           |        |          |          | <input type="checkbox"/> | <input type="checkbox"/> |

10. FILTER PACK

| Filter Material | From | To | Weight / Volume | Placement Method |
|-----------------|------|----|-----------------|------------------|
|                 |      |    |                 |                  |

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

111 ft. below ground Artesian pressure \_\_\_\_\_ lb.  
Depth flow encountered \_\_\_\_\_ ft. Describe access port or control devices:

Top of casing  
39N 5W 16

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

| Yield gal./min. | Drawdown | Pumping Level | Time            |
|-----------------|----------|---------------|-----------------|
| <u>250</u>      |          |               | <u>1.50 hrs</u> |

Water Temp. 56.0 Bottom hole temp. \_\_\_\_\_

Water Quality test or comments: Good

Depth first Water Encounter 161

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

| Bore Dia. | From | To  | Remarks: Lithology, Water Quality & Temperature | Water |
|-----------|------|-----|-------------------------------------------------|-------|
| 12        | 0    | 47  | Brown clay                                      |       |
| 12        | 47   | 53  | Sandy clay                                      |       |
| 12        | 53   | 105 | White Sticky clay                               |       |
| 12        | 105  | 120 | Blk BSLT                                        |       |
| 8         | 120  | 161 | Hd Blk BSLT                                     |       |
| 8         | 161  | 167 | Green Seams on Blk BSLT                         |       |
| 8         | 167  | 255 | HARD Blk BSLT                                   |       |
| 7         | 255  | 280 | Green Seams on Blk BSLT                         |       |

RECEIVED

MAY 1 2003

IDWR/North

Completed Depth 280 (Measurable)  
Date: Started 3-19-03 Completed 3-30-03

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name UHLENKOTT DRILLING Firm No. 125

Principal Driller Jim Uhlenkott Date 4-9-03

and Driller or Operator II Jim Uhlenkott Date 4-9-03

Operator I \_\_\_\_\_ Date \_\_\_\_\_

Principal Driller and Rig Operator Required.  
Operator I must have signature of Driller/Operator II.

I am Daniel P. Mack, the owner of Rambler RV LLC and Renaissance Properties LLC. I want to keep the water right license under the name Renaissance Properties LLC because it will maintain consistency with the ownership name with the Idaho Department of Environmental Quality.



7/27/2020

Daniel P. Mack

SCANNED  
JUL 27 2020