

Identify

Identify from:  Parcels

- ☐ Parcels
 - BANISTER, BRIAN A

Location: 2,271,442.540 1,721,554.747 Meters

Field	Value
ID	11832396
UPDATED	1/22/2020
PIN	RP38N05W080617
OWNER	BANISTER, BRIAN A
ADDRESS1	1111 EID ROAD
ADDRESS2	
CITY	MOSCOW
STATE	ID
ZIPCODE	83843
P_ADDRESS	1111 EID RD
P_ZIPCODE	83843
SUB_NAME	
LEGAL1	23.29 AC TAX #5409
LEGAL2	8 38 5
LEGAL3	
LEGAL4	
LEGAL5	
LEGAL6	
ACRES	22
COUNTY	Latah
SOURCE	<null>
YEAR_BUILT	2000

Identified 1 feature

 Table Of Contents  Identify

RECEIVED

Form 238-7

3/95 JUN 22 1998

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

77438

NORTHERN REGION

1. DRILLING PERMIT NO.

Other IDWR N: 87-98-N-8

2. OWNER:

Name: Jerry Bliler

Address: 218 E. Morton

City: Moscow State: ID Zip: 83843

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

Sketch map location must agree with written location.

Twp. 38 N North ☒ or South ☐
 Rge. 5 East ☐ or West ☐
 Sec. 8 1/4 NW 1/4 NE 1/4
 Gov't Lot _____ County: Latah
 Lat: _____ Long: _____
 Address of Well Site: 1111 Eld Road
 City: Genesee

(Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
benit	0	101	300 lbs	dry

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) _____

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8	71	101	250	Steel	☒	☐	☒	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

- ☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

84 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices: _____

38 N 5 W 8

11. WELL TESTS:

- ☐ Pump ☐ Bailor ☐ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
approx. 5		255	3 min.

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

12. LITHOLOGIC LOG: (Describe repairs or abandonment) Depth first Water Encountered 186

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	25	overburden		☒
10	25	92	dec. granit		☒
10	92	61	granit, firm		☒
8	101	186	granit, firm		☒
8	186	188	Fract. granit		☒
8	188	224	granit, firm		☒
8	224	226	Fract. granit		☒
8	226	235	granit, firm		☒
8	235	241	soft granit		☒
8	241	247	granit, firm		☒
8	247	251	soft granit		☒
8	251	254	granit, firm		☒
8	254	257	Fract. granit		☒
8	257	261	granit, firm		☒

Completed Depth 261 (Measurable)

Date: Started 4/1/98 Completed 4/15/98

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name: WITT Well Drilling Firm No. 58

Firm Official: Roger Witt Date: 6/16/98

and _____

Supervisor or Operator _____ Date _____

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES