

FIELD EXAMINATION OF PRBA WATER RIGHT CLAIM

Claim Identification Number: 87-11847

Date of Examination: 9/22/2020

Approximate Time of Examination: 3:00pm

IDWR Field Staff: Christopher Holmes

Point of Contact: None

Examination Location: 1311 Marshall Rd, Viola ID 83872

Purpose of Visit: Determine if the source exists on claimant's property.

Field Examination Notes:

The purpose of the visit was to determine if there is a creek on the property where the claimant claimed. According to DRG and NHDPlus_HR map on ArcMap, West Fork of Flannigan Creek is located to the west of the parcel and also across the road, but not on the claimant's property.

The claimant did not return my phone call requesting them to give me a call back. I was in the area for a separate field exam, and decided to see what information I could gather on the roadside by the claimant's parcel. I stayed on the roadside and did not enter onto private property. From the roadside, I could visibly see a channel that still had water located where the claimant claimed, figures 2-4. There is a culvert that allows the water to flow north under the road, figure 1 on the south side of the road and figure 5 on the north side.

After conducting the field exam, and in conjunction with ArcMap DRG and NHDPlus_HR mapping, I recommend that the source is unnamed stream, tributary to West Fork Flannigan Creek.



Figure 1



Figure 2



Figure 3



Figure 4



Figure 5



Figure 6