RECEIVED

Form 238-7

SEP 25 1997 POSTED

NORTHERN REGION IDWR

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

96103

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 87-97-N-43
Other IDWR No. D0003142

2. OWNER:
Name Kirby Baerbier Sr.
Address 7512 137th Ave Se
City Snohomish State Wa Zip 98290

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 41 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 13, SW 1/4 (10 acres) SE 1/4 (40 acres) ____ 1/4 (160 acres)
Gov't Lot ____ County Latah
Lat: : : Long: : :
Address of Well Site ½ mile off Lindsay Cutoff - Left Side City Potlatch
(Give at least name of road & Distance to Road or Landmark)

Lt.____ Blk.____ Sub. Name____

4. USE:
☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other____

5. TYPE OF WORK check all that apply (Replacement etc.)
☒ New Well ☐ Modify ☐ Abandonment ☐ Other____

6. DRILL METHOD
☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	55	16	Dry Pour

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 55
Was drive shoe seal tested? ☒ Y ☐ N How? Air

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8"	~~45~~	55	.025	Steel	☒	☐	☒	☐
6"	-10	210		PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe____ Length of Tailpipe____

9. PERFORATIONS/SCREENS
☒ Perforations Method Skill Saw
☐ Screens Screen Type____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
220	210	6/1/4	60	6"	PVC	☐	☒
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
70 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 150 ft. Describe access port or control devices: Removable Well Cap

SWSE 13 41N 5W

11. WELL TESTS:
☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
65		200	2hr

Water Temp. 49° Bottom hole temp. ____
Water Quality test or comments: Clear
Depth first Water Encountered 150

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
10	0	1	Soil		
10	1	50	Clay		
10	50	55	Basalt		
8	55	75	Basalt		
8	75	90	Clay		
8	90	100	Sandstone		
8	100	120	Basalt		
8	120	130	Sandstone		
8	130	135	Basalt		
8	135	140	Sandstone		
8	140	210	Basalt	☒	

Completed Depth 210' (Measurable)
Date: Started 9-15-97 Completed 9-21-97

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Bayers Well Drilling Firm No. 103
Firm Official [signature] Date 9-23-97
and
Supervisor or Operator [signature] Date 9-23-97
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES