

RECEIVED

Form 238-7

3/95 JUL 09 1996

NORTH IDWR



IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT 96088

Use Typewriter or Ballpoint Pen

Office Use Only
 Inspected by _____
 Twp _____ Rge _____ Sec _____
 1/4 _____ 1/4 _____ 1/4 _____
 Lat: _____ Long: _____
☒ Air ☐ Flowing Artesian

1. DRILLING PERMIT NO. 87-96-N-22
 Other IDWR No. _____

2. OWNER: Louis Larsen
 Name _____
 Address 11441 Skyway Road
 City Lansdale Calif State _____ Zip 91040-2044

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

North ☒ or South ☐
 East ☐ or West ☒
 Twp. 41 Rge. 4 Sec. 16
 Gov't Lot _____ 1/4 SW 1/4 SW 1/4
 Lat: _____ Long: _____
 Address of Well Site _____ City _____
 (Give at least name of road + Distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

- ☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

- ☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD

- ☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
<i>Bentonite</i>	<i>0</i>	<i>18</i>	<i>15 #</i>	<i>Bag</i>

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____

Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
<u>6"</u>	<u>+2</u>	<u>18</u>	<u>208</u>	<u>Steel</u>	☒	☐	☒	☐
<u>4 1/2"</u>	<u>+7</u>	<u>103</u>	<u>160</u>	<u>PVC</u>	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

9. PERFORATIONS/SCREENS

- ☐ Perforations Method _____
☐ Screens Screen Type _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
						☐	☐
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

20 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered _____ ft. Describe access port or control devices:
SWSW 16 4IN 4W

11. WELL TESTS:

- ☐ Pump ☐ Bailer

Yield gal./min.	Drawdown	Pumping Level	Time
<u>60 gpm</u>			

Water Temp. _____ Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encountered _____

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
<u>8</u>	<u>0</u>	<u>1</u>	<u>dirt</u>		☒
<u>8</u>	<u>1</u>	<u>16</u>	<u>hard med basalt</u>		☒
<u>8</u>	<u>16</u>	<u>20</u>	<u>med basalt</u>		☒
<u>6 7/8</u>	<u>74</u>	<u>74</u>	<u>med basalt</u>		☒
<u>6</u>	<u>74</u>	<u>100</u>	<u>med soft basalt</u>	☒	

Completed Depth 100 ft (Measurable)
 Date: Started June 6, 96 Completed June 7, 96

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Uhlenkott Drilling Firm No. 125

Firm Official Ray Uhlenkott Date July 4, 96

and Supervisor or Operator Jim Uhlenkott Date July 4, 96

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES