RECEIVED 11/23/99

NOV 10 1999

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

076436

IDWR/North

Office Use Only
Inspected by
Twp ____ Rge ____ Sec ____
____ 1/4 ____ 1/4 ____ 1/4
Lat: : : Long: : :

1. WELL TAG NO. D 00 10595

DRILLING PERMIT NO. 87-99-N-32

Other IDWR No.

2. OWNER:

Name CARL HAKIMIAN

Address 2410 BIZIN Rd

City MOSCOW State ID Zip 83843

POSTED

3. LOCATION OF WELL by legal description:

Sketch map location must agree with written location.

N / W / E / S — X in SW 1/4 SW 1/4

Twp. 41 North ☒ or South ☐

Rge. 5 East ☐ or West ☒

Sec. 22 ____ 1/4 SW 1/4 SW 1/4 (10 acres / 40 acres / 160 acres)

Gov't Lot ____ County LATAH

Lat: : : Long: : :

Address of Well Site 5 miles

East of (Give at least name of road + Distance to Road or Landmark)

City VIOLA

Lt. ____ Blk. ____ Sub. Name ____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation

☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
Bentonite	0	18	150	Top Pour

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) ____

Was drive shoe seal tested? ☒ Y ☐ N How? Air Pressure

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	+2	-18	250	steel	☒	☐	☒	☐
4½	-5	-300	160	PVC	☐	☒	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS

☒ Perforations Method SAW

Screens Screen Type ____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
-270	-300	1/8-4	56	4½	PVC	☐	☒
5						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

41 ft. below ground Artesian pressure — lb.

Depth flow encountered — ft. Describe access port or control devices: Top of casing

11. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
4			1.00

Water Temp. 55-0 Bottom hole temp. ____

Water Quality test or comments: Good

Depth first Water Encounter 170

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
8	0	15	Soft White Granite		✓
8	15	18	Med Brown White Granite		✓
6	18	170	" " " "		✓
6	170	265	Med Hard Green Granite	3.5	
6	265	300	Hard Green Granite	.5	

Completed Depth 300 ft (Measurable)

Date: Started 11/1/99 Completed 11/2/99

13. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name UHLENKOTT DRILLING Firm No. 125

Firm Official Tom Uhlenkott Date 11-5-99

and

Driller or Operator Dave Richards Date 11-5-99

(Sign once if Firm Official & Operator)

41 N 5 W 22

FORWARD WHITE COPY TO WATER RESOURCES