

IDAHO DEPARTMENT OF WATER RESOURCES

WELL DRILLER'S REPORT

RECEIVED

JUL 14 2003

IDWR/North

Office Use Only			
Well ID No. _____			
Inspected by _____			
Twp. _____	Rge. _____	Sec. _____	
_____ 1/4	_____ 1/4	_____ 1/4	
Lat: _____	_____	Long: _____	_____

1. WELL TAG NO. D 00028534
 DRILLING PERMIT NO. 803639
 Water Right or Injection Well No. _____

2. OWNER:

Name Dave Mendenhall
 Address 3404 Foothill Rd.
 City Moscow State ID Zip 83843

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 40 North ☒ or South ☐
 Rge. 5 East ☐ or West ☒
 Sec. 21 1/4 NW 1/4 SW 1/4
 Gov't Lot _____ County _____

Lat: _____ Long: _____
 Address of Well Site Lewis Rd. + Foothills
 City Moscow

(Give at least name of road + Distance to Road or Landmark)
 Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

5. TYPE OF WORK check all that apply

(Replacement etc.)

☐ New Well ☒ Modify ☐ Abandonment ☐ Other

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method

Was drive shoe used? ☐ Y ☐ N Shoe Depth(s) _____Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
4"	5	228	160	PVC	☐	☒	☐	☐
					☐	☐	☐	☐
					☐	☐	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

9. PERFORATIONS SCREENS PACKER TYPE

Perforation Method Drill

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
238	258	1"	10	4"	PVC	☐	☒
						☐	☐
						☐	☐

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

28 ft. below ground Artesian pressure _____ lb.
 Depth flow encountered 125 ft. Describe access port or control devices: _____

40N 5W 21

12. WELL TESTS:

☐ Pump ☐ Bailor ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
11 gpm	Air-lift from 278		

Water Temp. 52°

Bottom hole temp. _____

Water Quality test or comments: Clear no odorDepth first Water Encounter 125

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
			Well has About 30' of 8" Casing, 78' Deep w/2gpm		
8"	78	93	Granit Decomposed yellow & Black		
	93	96	Granit - Black & white		
	96	102	Granit - Decomposed - yellow & Brown		
	102	125	Granit Black & white		
	125	130	Granit - Black & white w/water 3 gpm		
	130	170	Granit - Black & white		
	170	178	Granit - Black & white w/water 5 gpm		
	178	278	Granit Black & white		
			11 gpm Total @ 278		

SCANNED

MAR 05 2021

Completed Depth 278 (Measurable)Date: Started 6-12-03 Completed 6-13-03

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name All-Pays Drilling Inc. Firm No. 510Principal Driller Stanley G. Wolfe Date 7-7-03Driller or Operator II Alvin Catris Date 7-7-03

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
 Operator I must have signature of Driller/Operator II.

FORWARD WHITE COPY TO WATER RESOURCES