

0927771

☒ Air ☐ Flowing Artesian

Temperature of water _____ Was a water analysis done? Yes ☐ No ☒

By whom? _____

Water Quality (odor, etc.) _____

Bottom Hole Temperature _____

36 ft. below surface Depth artesian flow found

Artesian pressure 1b. Describe access port

Describe Controlling Devices: _____

Lot No. _____ Block No. _____ Subd. Name _____

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other

☒ New Well ☐ Modify or Repair ☐ Replacement ☐ Abandonment

☐ Mud Rotary ☒ Air Rotary ☐ Cable ☐ Other _____

SEAL/FILTER PACK			AMOUNT	METHOD
Material	From	To	Sacks or Pounds	
BENTONITE ~~SLURRY~~	1	113'	4	Pumped
SLURRY				

Was drive shoe seal tested? ☒ YES ☐ NO How? Leak Test

Diameter	From	To	Gauge	Casting	Liner	Steel	Plastic	Welded	Threaded
8	41	113'	250			☒	☐	☒	☐
						☐	☐	☐	☐
						☐	☐	☐	☐
						☐	☐	☐	☐

Final location of shoes _____

Top Packer or Headpipe _____ Bottom Tailpipe _____

☐ Perforations	Method	_____
☐ Screens	Type	_____
	Material	_____

From	To	Slot Size	Number	Diameter	Tele/Pipe Size	Casting	Linear
							
							
							
							

NENE 8 41N 4w

[illegible]

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

McPHERSON & WRIGHT DRILLING

Firm Name 2246 Burrell Firm No. 376

2240 Burrell
Lewiston, Idaho 83501

Firm Official Chas McPherson Date 1-6-94

and (206) 743-7295

Supervisor or Operator *J. P. [Signature]* Date *1-6-94*

(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES