Form 238-87
3/95

RECEIVED
AUG 22 2002
IDWR/North

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Use Typewriter or Ballpoint Pen

Office Use Only
Inspected by _____
Twp____ Rge____ Sec____
____1/4 ____1/4 ____1/4
Lat: : : Long: : :

1. DRILLING PERMIT NO. 000-22507
Other IDWR No. 780619

2. OWNER:
Name Judd & Best LLP
Address 123 W 7th St
City Moscow State ID Zip 83843

POST-IT

3. LOCATION OF WELL by legal description:
Sketch map location must agree with written location.

N / W / E / S

Twp. 39 North ☑ or South ☐
Rge. 5 East ☐ or West ☑
Sec. 19 , ____ 1/4 NE 1/4 NE 1/4
(10 acres) (160 acres)
Gov't Lot ____ County Latah
Lat: : : Long: : :
Address of Well Site Entering Moscow
07 95 South City Moscow
(Give at least name of road + Distance to Road or Landmark)
Lt. 2 Blk. ____ Sub. Name Felsted K

4. USE:
☑ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other ____

5. TYPE OF WORK check all that apply (Replacement etc.)
☑ New Well ☐ Modify ☐ Abandonment ☐ Other ____

6. DRILL METHOD
☑ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other ____

7. SEALING PROCEDURES

SEAL/FILTER PACK Material	From	To	AMOUNT Sacks or Pounds	METHOD
cement	0	35	25 bags	pump down

Was drive shoe used? ☐ Y ☑ N Shoe Depth(s) ____
Was drive shoe seal tested? ☐ Y ☐ N How? ____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8"	+2	64	250	steel	☑	☐	☑	☐
6"	-38	78			☐	☑	☐	☐
					☐	☐	☐	☐

Length of Headpipe ____ Length of Tailpipe ____

9. PERFORATIONS/SCREENS
☑ Perforations Method saw cuts
☐ Screens Screen Type ____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
-38	72	1/8X3	200		PVC	☐	☑
						☐	☐
						☐	☐

10. STATIC WATER LEVEL OR ARTESIAN PRESSURE:
29 ft. below ground Artesian pressure ____ lb.
Depth flow encountered 64 ft. Describe access port or control devices: Top of Well

39N 5W 19

11. WELL TESTS:
☐ Pump ☐ Bailer ☑ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
25 gpm			1.5

Water Temp. 54° Bottom hole temp. 54°
Water Quality test or comments: Good
Depth first Water Encountered 64

12. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Water Y	Water N
12	0	46	clay		
	46	58	brown clay		
8	58	62	soft basalt		
	62	78	soft brown basalt	☑	
			caved back to 72 ft		
			25 gpm		

Completed Depth 72 ft (Measurable)
Date: Started July 16, 02 Completed July 22, 02

13. DRILLER'S CERTIFICATION
I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Firm Name Jim Ulbrickson Drilling Firm No. 125
Firm Official Jim Ulbrickson Date 8/7/02
and
Supervisor or Operator ____ Date 8/7/02
(Sign once if Firm Official & Operator)

FORWARD WHITE COPY TO WATER RESOURCES