

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT1. WELL TAG NO. D D0051801
DRILLING PERMIT NO. 816978
Water Right or Injection Well No. _____

2. OWNER:

Name Larry Gormer
Address 140 East Palouse River Drive
City Moscow State ID Zip 83843

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub, or Directions to well.

Twp. 39 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 30 1/4 NW 1/4 NE 1/4
Gov't Lot - County LatahLat: _____ Long: _____
Address of Well Site 3055 Highway 95
(Give at least name of road + Distance to Road or Landmark) City MoscowLt. 40 Blk. _____ Sub. Name SKY View

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply (Replacement etc.)

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite	0	-38	400	Top Pear

Was drive shoe used? ☐ Y ☒ N Shoe Depth(s) _____Was drive shoe seal tested? ☐ Y ☐ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
6"	0	-38	250	Steel	☒	☐	☒	☐
4.5"	30	-150	160	Pvc	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method Saw

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
110	150	8x4	42	4.5	Pvc	☐	☒

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

82 ft. below ground Artesian pressure _____ lb.

Depth flow encountered _____ ft. Describe access port or control devices: _____

Top of casing39N 5W 30

Office Use Only			
Well ID No. _____			
Inspected by _____			
Twp. _____	Rge. _____	Sec. _____	
_____ 1/4	_____ 1/4	_____ 1/4	
Lat: _____	_____	Long: _____	_____

12. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
10			1.5

Water Temp. 55° Bottom hole temp _____Water Quality test or comments: GoodDepth first Water Encounter 125

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Bore Dia	From	To	Remarks: Lithology, Water Quality & Temperature	Water	Y	N
10	0	36	Brown Clay			
10	36	38	Med Hd Granite			
6	38	125	" "			
6	125	130	Soft Br Granite	10		
6	130	150	Med Hd Granite			

RECEIVED

MAY 07 2007

DWR/North

Completed Depth 150' (Measurable)Date: Started 5-31-07 Completed 5-31-07

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Uhlen Rott Drilling Firm No. 125Principal Driller Thom Uhlen Rott Date 5-31-07and Driller or Operator II _____ Date 5-31-07

Operator I _____ Date _____

Principal Driller and Rig Operator Required
Operator I must have signature of Driller/Operator II. **SCANNED**
MAY 17 2019