

Form 238-7
6/02

IDAHO DEPARTMENT OF WATER RESOURCES
WELL DRILLER'S REPORT

Office Use Only			
Well ID No.			
Inspected by			
Twp	Rge	Sec	
1/4	1/4	1/4	
Lat:	:	Long:	:

1. WELL TAG NO. D 0039835

DRILLING PERMIT NO. 830192

Water Right or Injection Well No. _____

2. OWNER:

Name Mike Hinson
Address 1174 Idlers Rest Rd
City Moscow State Id Zip 83843

3. LOCATION OF WELL by legal description:

You must provide address or Lot, Blk, Sub. or Directions to well.

Twp. 39 North ☒ or South ☐
Rge. 5 East ☐ or West ☒
Sec. 7 SE 1/4 SE 1/4 1/4
Gov't Lot _____ County Latah

Lat: _____ Long: _____
Address of Well Site South of 5205 Robinson
Lake Rd. City Moscow
(Give at least name of road + distance to Road or Landmark)

Lt. _____ Blk. _____ Sub. Name _____

4. USE:

☒ Domestic ☐ Municipal ☐ Monitor ☐ Irrigation
☐ Thermal ☐ Injection ☐ Other _____

5. TYPE OF WORK check all that apply

☒ New Well ☐ Modify ☐ Abandonment ☐ Other _____ (Replacement etc.)

6. DRILL METHOD:

☒ Air Rotary ☐ Cable ☐ Mud Rotary ☐ Other _____

7. SEALING PROCEDURES

Seal Material	From	To	Weight / Volume	Seal Placement Method
Bentonite	0	38	300 lbs	Dry

Was drive shoe used? ☒ Y ☐ N Shoe Depth(s) 38

Was drive shoe seal tested? ☐ Y ☒ N How? _____

8. CASING/LINER:

Diameter	From	To	Gauge	Material	Casing	Liner	Welded	Threaded
8	+1	38	250	Steel	☒	☐	☒	☐
6	-10	404	160 B	PVC	☐	☒	☐	☐

Length of Headpipe _____ Length of Tailpipe _____

Packer ☐ Y ☒ N Type _____

9. PERFORATIONS/SCREENS PACKER TYPE

Perforation Method Saw

Screen Type & Method of Installation _____

From	To	Slot Size	Number	Diameter	Material	Casing	Liner
369	404	1/2 x 8	30	6	PVC	☐	☒

10. FILTER PACK

Filter Material	From	To	Weight / Volume	Placement Method

11. STATIC WATER LEVEL OR ARTESIAN PRESSURE:

25 ft. below ground Artesian pressure _____ lb.
Depth flow encountered _____ ft. Describe access port or control devices: _____

12. WELL TESTS:

☐ Pump ☐ Bailer ☒ Air ☐ Flowing Artesian

Yield gal./min.	Drawdown	Pumping Level	Time
approx 1		400	1 Hr.

Water Temp. _____

Bottom hole temp. _____

Water Quality test or comments: _____

Depth first Water Encounter 232

13. LITHOLOGIC LOG: (Describe repairs or abandonment)

Water

Bore Dia.	From	To	Remarks: Lithology, Water Quality & Temperature	Y	N
10	0	10	overburden		☒
10	10	28	dec. granit		☒
10	28	38	granit, firm		☒
8	38	54	granit, firm		☒
8	54	68	soft granit		☒
8	68	76	granit, firm		☒
8	76	82	granit, soft		☒
8	82	404	granit, firm	☒	

RECEIVED

JUN 01 2005

IDWR/North

Completed Depth 404 (Measurable)

Date: Started 2/24/05 Completed 3/1/05

14. DRILLER'S CERTIFICATION

I/We certify that all minimum well construction standards were complied with at the time the rig was removed.

Company Name Wittwell Drilling Firm No. 58

Principal Driller Roger Witt Date 3/2/05

and Driller or Operator II _____ Date _____

Operator I _____ Date _____

Principal Driller and Rig Operator Required.
Operator I must have signature of Driller/Operator II.

FORWARD WHITE COPY TO WATER RESOURCES